

=====
*** Basic Information ***
=====

[Create date] 2018/03/06

[Program Name] LCT_SIBERIA-H

[Version] 01.000:03

[PCB No.] D3ET5210B

[Interchangeability] X / O

[Other Firmware Requirements] None

[PCB Requirements] None

[Software category] Normal Release

[Release category] Normal Release

[Program category] Firmware

Exported to(language) GEN(all)

[Firmware No.] D3ET5260A

[File Information]

File Name D3ET5260A.fwu

File Type Module for Service

Size 0.13 MB (131568 byte)

[Availability of RFU] No

[Production reflection] 2017/12

=====
*** Note ***
=====

[Note]

=====
*** Important Notes ***
=====

[Important Notes]

=====
*** Modification History ***
=====

=====

[Modifications made:]
Rank D

1st Mass production

[Modification history]

=====
*** Basic Information ***
=====

[Create date] 2018/12/18

[Program Name] LCT_SIBERIA-H

[Version] 01.000:03

[PCB No.] D3ET5210B

[Interchangeability] X / O

[Other Firmware Requirements] None

[PCB Requirements] None

[Software category] Normal Release

[Release category] Normal Release

[Program category] Firmware

Exported to(language) GEN(all)

[Firmware No.] D3ET5260A

[File Information]

File Name D3ET5260A.fwu

File Type Module for Service

Size 0.13 MB (131568 byte)

[Availability of RFU] No

[Production reflection] 2017/12

=====
*** Note ***
=====

[Note]

=====
*** Important Notes ***
=====

[Important Notes]

=====
*** Modification History ***
=====

[Modifications made:]

Rank C

Symptom corrected:
Even when an error occurs with multiple cooling fans, SC is alerted
only for the last fan detected of the error.

[Modification history]

Version 01.000:03
Rank D

1st Mass production