

=====
*** Basic Information ***
=====

[Create date] 2018/03/27

[Program Name] LCT1_ANATOLIA-B

[Version] 01.010:02

[PCB No.] D3EW5151

[Interchangeability] X / O

[Other Firmware Requirements] None

[PCB Requirements] None

[Software category] Normal Release

[Release category] Normal Release

[Program category] Firmware

Exported to(language) GEN(all)

[Firmware No.] D3EW5260D_LCT1

[File Information]

File Name D3EW5260D_LCT1.fwu

File Type Module for Service

Size 0.25 MB (262644 byte)

[Availability of RFU] No

[Production reflection] 2018/03

=====
*** Note ***
=====

[Note]

=====
*** Important Notes ***
=====

[Important Notes]

=====
*** Modification History ***
=====

=====
[Modifications made:]

Rank C

Symptom Corrected:

- Misfeeds may occur when the tray reaches near empty status because the bottom plate of the tray does not ascend fast enough.

NOTE: This corrected applies only when the Vacuum Feed Tray is connected to main units other than the ProC7200 series.

[Modification history]

Version 01.000:02

Rank D

1st Mass production

=====
*** Basic Information ***
=====

[Create date] 2018/03/27

[Program Name] LCT2_ANATOLIA-B

[Version] 01.010:02

[PCB No.] D3EW5151

[Interchangeability] X / O

[Other Firmware Requirements] None

[PCB Requirements] None

[Software category] Normal Release

[Release category] Normal Release

[Program category] Firmware

Exported to(language) GEN(all)

[Firmware No.] D3EW5260D_LCT2

[File Information]

File Name D3EW5260D_LCT2.fwu

File Type Module for Service

Size 0.25 MB (262644 byte)

[Availability of RFU] No

[Production reflection] 2018/03

=====
*** Note ***
=====

[Note]

=====
*** Important Notes ***
=====

[Important Notes]

=====
*** Modification History ***
=====

=====
[Modifications made:]

Rank C

Symptom Corrected:

- Misfeeds may occur when the tray reaches near empty status because the bottom plate of the tray does not ascend fast enough.

NOTE: This corrected applies only when the Vacuum Feed Tray is connected to main units other than the ProC7200 series.

[Modification history]

Version 01.000:02

Rank D

1st Mass production

=====
*** Basic Information ***
=====

[Create date] 2018/03/27

[Program Name] LCT3_ANATOLIA-B

[Version] 01.010:02

[PCB No.] D3EW5151

[Interchangeability] X / O

[Other Firmware Requirements] None

[PCB Requirements] None

[Software category] Normal Release

[Release category] Normal Release

[Program category] Firmware

Exported to(language) GEN(all)

[Firmware No.] D3EW5260D_LCT3

[File Information]

File Name D3EW5260D_LCT3.fwu

File Type Module for Service

Size 0.25 MB (262644 byte)

[Availability of RFU] No

[Production reflection] 2018/03

=====
*** Note ***
=====

[Note]

=====
*** Important Notes ***
=====

[Important Notes]

=====
*** Modification History ***
=====

=====
*** Basic Information ***
=====

[Create date] 2019/01/11

[Program Name] LCT1_ANATOLIA-B

[Version] 02.000:02

[PCB No.] D3EW5152

[Interchangeability] X / O

[Other Firmware Requirements] None

[PCB Requirements] None

[Software category] Normal Release

[Release category] Normal Release

[Program category] Firmware

Exported to(language) GEN(all)

[Firmware No.] D3EW5260E_LCT1

[File Information]

File Name D3EW5260E_LCT1.fwu

File Type Module for Service

Size 0.25 MB (262644 byte)

[Availability of RFU] No

[Production reflection] 2019/02

=====
*** Note ***
=====

[Note]

=====
*** Important Notes ***
=====

[Important Notes]

=====
*** Modification History ***
=====

[Modifications made:]

Rank C

Symptom corrected:

- Remaining paper is notified as 50% even when approximately 60% of the tray is loaded.

[Modification history]

Version 01.010:02

Rank C

Symptom Corrected:

- Misfeeds may occur when the tray reaches near empty status because the bottom plate of the tray does not ascend fast enough.

NOTE: This corrected applies only when the Vacuum Feed Tray is connected to main units other than the ProC7200 series.

Version 01.000:02

Rank D

1st Mass production

=====
[Modifications made:]

Rank C

Symptom Corrected:

- Misfeeds may occur when the tray reaches near empty status because the bottom plate of the tray does not ascend fast enough.

NOTE: This corrected applies only when the Vacuum Feed Tray is connected to main units other than the ProC7200 series.

[Modification history]

Version 01.000:02

Rank D

1st Mass production

=====
*** Basic Information ***
=====

[Create date] 2019/01/11

[Program Name] LCT2_ANATOLIA-B

[Version] 02.000:02

[PCB No.] D3EW5152

[Interchangeability] X / O

[Other Firmware Requirements] None

[PCB Requirements] None

[Software category] Normal Release

[Release category] Normal Release

[Program category] Firmware

Exported to(language) GEN(all)

[Firmware No.] D3EW5260E_LCT2

[File Information]

File Name D3EW5260E_LCT2.fwu

File Type Module for Service

Size 0.25 MB (262644 byte)

[Availability of RFU] No

[Production reflection] 2019/02

=====
*** Note ***
=====

[Note]

=====
*** Important Notes ***
=====

[Important Notes]

=====
*** Modification History ***
=====

[Modifications made:]

Rank C

Symptom corrected:

- Remaining paper is notified as 50% even when approximately 60% of the tray is loaded.

[Modification history]

Version 01.010:02

Rank C

Symptom Corrected:

- Misfeeds may occur when the tray reaches near empty status because the bottom plate of the tray does not ascend fast enough.

NOTE: This corrected applies only when the Vacuum Feed Tray is connected to main units other than the ProC7200 series.

Version 01.000:02

Rank D

1st Mass production

=====
*** Basic Information ***
=====

[Create date] 2019/01/11

[Program Name] LCT3_ANATOLIA-B

[Version] 02.000:02

[PCB No.] D3EW5152

[Interchangeability] X / O

[Other Firmware Requirements] None

[PCB Requirements] None

[Software category] Normal Release

[Release category] Normal Release

[Program category] Firmware

Exported to(language) GEN(all)

[Firmware No.] D3EW5260E_LCT3

[File Information]

File Name D3EW5260E_LCT3.fwu

File Type Module for Service

Size 0.25 MB (262644 byte)

[Availability of RFU] No

[Production reflection] 2019/02

=====
*** Note ***
=====

[Note]

=====
*** Important Notes ***
=====

[Important Notes]

=====
*** Modification History ***
=====

[Modifications made:]

Rank C

Symptom corrected:

- Remaining paper is notified as 50% even when approximately 60% of the tray is loaded.

[Modification history]

Version 01.010:02

Rank C

Symptom Corrected:

- Misfeeds may occur when the tray reaches near empty status because the bottom plate of the tray does not ascend fast enough.

NOTE: This corrected applies only when the Vacuum Feed Tray is connected to main units other than the ProC7200 series.

Version 01.000:02

Rank D

1st Mass production