

Model: Internal Shift Tray SH3050		Date: 23-Feb-12	No.: RD583001
Subject: Parts Catalog Correction for Cam		Prepared by: T. Nihei	
From: 2nd Tech Service Sect., MFP/P Tech Service Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input checked="" type="checkbox"/> Part information <input type="checkbox"/> Action required <input type="checkbox"/> Mechanical <input type="checkbox"/> Electrical <input type="checkbox"/> Service manual revision <input type="checkbox"/> Paper path <input type="checkbox"/> Transmit/receive <input type="checkbox"/> Retrofit information <input type="checkbox"/> Product Safety <input type="checkbox"/> Other (      ) <input type="checkbox"/> Tier 2		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
D3884651	D6334651	CAM:SHIFT TRAY	1-1	X/X	-	-	Set as O/O.
B7914455	D6334455	LEVER:TORQUE LIMITER:SHIFT TRAY	1-1	X/X	-	-	

**Change:** The shapes of these parts were changed.

**Reason:** To further improve the function of these parts.

**Important:** If either of these parts needs to be replaced, make sure to install both of the new parts shown above **together as a set.**