RICOH

Technical Bulletin

Reissued: 15-Mar-12

No.: RD585001a

RTB Reissue

The items in bold italics have been corrected or added.

Subject: Firmware Release Note: 500-sheet Finisher (SR3070)			Prepared by: S. Hayami		
From: 1st Tech S	ervice Sect., MFP/Printer Tech				
Classification:	ification: Troubleshooting Part informati		ion	Action required	
	Mechanical	Electrical		Service manual revision	
	Paper path	Transmit/rec	eive 🗌	Retrofit information	
	Product Safety	Other (Firmv	vare) 🖂] Tier 2	

This RTB has been issued to announce the firmware release information for the **500-sheet Finisher (SR3070).**

Version	Program No.	Effective Date	Availability of RFU		
01.030:01	D5855300C	January 2012 production	Available		
01.020:01	D5855300B	1st Mass production	Available		

Note: Definition of Availability of RFU via @Remote

"Available" The firmware can be updated via RFU or SD card.

"Not available": The firmware can only be updated via SD card.

Version	Modified Points or Symptom Corrected
01.030:01	Symptom corrected:
	Jam 166 may occur when thin paper is used.
01.020:01	1st Mass production

RICOH

Technical Bulletin

PAGE: 1/1

Model: 500-sheet Finisher (SR3070)			Date: 25-Nov-15			No.: RD585002
Subject: Parts catalog correction "6.Stapler Unit (D585)"			Prepared by: Jun Kitagawa			
From: 1st Tech Service Sect. MFP/P Tech Service Dept.			pt.	 		
Classification:	 Troubleshooting Mechanical Paper path Product Safety 	Part info	al	eive] Servic	required e manual revision it information

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
_	D3721411	STAY:COUPLING	1	-	13	31	

Change: The Stay outlined in red was registered as a service part.

12

Reason: To meet requests from the field.

6.Stapler Unit (D585)

