RICOH

Modification Bulletin

Reissued: 28-Apr-08

Model: Bellini-C3 Punch Unit PU5000(VICTORIA-E) Date: 18-Mar-08

No.: MB831001a

MB Reissue

The items in *bold italics* were corrected or added.

Modified Article:	Guide Plate	Prepared by: S. Ishizu						
From: 2nd Tech. S	upport Sec. Service Support							
Reason for	Parts catalog correction	Vendor cha	ange	Other				
Modification:	To facilitate assembly	🛛 To improve	e reliability	To meet standards	i			
	Part standardization	Product Sa	afety	()				

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
B8313211	B8313212	Guide Plate (-01)	1	X/O	3	10	
-	B8314212	Guide Plate (-02)	1	-	3	10	
-	B8315212	Guide Plate (-03)	1	-	3	10	

Change:

- 1) The surface and edges of the guide plate were made smoother.
- 2) New parts were added.

Reason:

- 1) To make the plate easier to handle.
- 2) These parts were missing from the Parts Catalog.

RICOH

Part Change Information List

	PCIL	PCIL	Old	New											
Model Code	Number	Correction	part number	part number	Description	Old Q'ty	New Q'ty Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number
Bellini-C3 Punch Unit PU5000(VICTORIA-E) B831	200903	Add		B5317350	COVER:PUNCH	0	1		2	26			Y		V0900373

Date: March 18, 2009

Reissued Date: March 23, 2009

RICOH

Part Change Information List

Date: August 31, 2009

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number		Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
Katana-C1 Punch Unit PU5000	B831	200908			B5317350	COVER:PUNCH		() -	1		2	20	6		Y	RB831001	V0900373	9010728