

| | | |
|------------------------------|----------------|---------------|
| Model: Bellini-C3 Punch Unit | Date:21-Aug-09 | No.: RB831001 |
|------------------------------|----------------|---------------|

| | | | |
|---|---|--|---|
| Subject: COVER:PUNCH | | Prepared by: T.Tadokoro | |
| From: PPMC Service Planning Department 1G | | | |
| Classification: | <input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Other () | <input checked="" type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive | <input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information |

1. PUNCH UNIT (B831)

| Old part number | New part number | Description | Q'ty | Int | Page | Index | Note |
|-----------------|-----------------|-------------|------|-----|------|-------|-----------|
| - | B5317350 | COVER:PUNCH | 0-1 | - | 2 | 26 | New Index |

Change: The following part (index#26) was added as a service part.

Reason: To further protect the inside of the Punch Unit from being touched.

Note: There is a small possibility of the above case, so this part isn't applied to the punch units which have already been installed in the field.

