

Model: Bellini-C2 Punch Unit	Date:8-Apr-09	No.: RB531001
------------------------------	---------------	---------------

Subject: COVER:PUNCH		Prepared by: T.Toriumi	
From: 2nd Tech. Support Sec. Service Support Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Other ()	<input checked="" type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information

1. PUNCH UNIT (B531)

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
-	B5317350	COVER:PUNCH	0-1	-	3	38	New Index

Change: The following part (index#38) was added as a service part.

Reason: To further protect the inside of the Punch Unit from being touched.

Note: There is a small possibility of the above case, so this part isn't applied to the punch units which have already been sent to the field.

RCL (Japan) Production (B531)

MODEL NAME	DESTINATION	CODE	SERIAL NO.
PUNCH UNIT TYPE 1075 NA	North America	B531-17	J5190200001
PUNCH UNIT TYPE 1075 EU	Europe	B531-27	J5190200163

