

Model: Z-folding Unit ZF4000		Date: 8-Feb-08	No.: MB660A01
Modified Article: Main Board		Prepared by: H.Matsui	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Part standardization	<input type="checkbox"/> Vendor change <input checked="" type="checkbox"/> To improve reliability <input type="checkbox"/> Other	<input type="checkbox"/> To meet standards ()

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B6605543	B6605548	PCB Main Control	1-1	X/O	23	9	

Change: The part numbers in the table were changed.

Reason: To support D014/D015 copier.

Model: Bellini-C2/Martini-C2 Z-folding Unit		Date: 28-Mar-08	No.: MB660003
Modified Article: Harness – Inlet		Prepared by: S. Ishizu	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	<input checked="" type="checkbox"/> Parts catalog correction <input type="checkbox"/> Vendor change <input type="checkbox"/> Other <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability <input type="checkbox"/> To meet standards <input type="checkbox"/> Part standardization <input type="checkbox"/> Product Safety ()		

Incorrect part number	Correct part number	Description	Q'ty	Int	Page	Index	Note
B6605233	B6605245	Harness – Inlet	1	14	23		

Change/Reason: The part number in the Parts Catalog was corrected.

Model: Bellini-C2/Martini-C2 Z-folding Unit		Date: 28-Mar-08	No.: MB660004
Modified Article: Harness – Power Source		Prepared by: S. Ishizu	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> Vendor change <input checked="" type="checkbox"/> Other <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability <input type="checkbox"/> To meet standards <input type="checkbox"/> Part standardization <input type="checkbox"/> Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B6605185	B6605186	Harness – Power Source	1	O/O	23	26	
B6605211	B6605212	Harness – AC Power Supply	1	O/O	23	35	
B6605215	B6605216	Harness – AC Power Supply	1	O/O	23	22	
B6605231	B6605234	Harness – AC Power Supply	1	O/O	23	25	

Change: The materials of these parts were changed.

Reason: To comply with revisions made to Ricoh's internal product safety standards.

Reissued: 3-Jun-08

Model: Z-folding Unit ZF4000	Date: 12-May-08	No.: MB660A03a
------------------------------	-----------------	----------------

MB Reissue

The items in ***bold italics*** were corrected or added.

Modified Article: PCB Main Control		Prepared by: S. Ishizu	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction	<input type="checkbox"/> Vendor change	<input type="checkbox"/> Other
	<input type="checkbox"/> To facilitate assembly	<input checked="" type="checkbox"/> To improve reliability	<input type="checkbox"/> To meet standards
	<input type="checkbox"/> Part standardization	<input type="checkbox"/> Product Safety	()


Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B6605547	B6605548	PCB Main Control	1	X/O	23	9	
	B6605510	EP-ROM	1	-	23	37*	New Index

Change:


- The following symptom was corrected:
The "Copying" message remains displayed if a jam occurs at the entrance of the Z-folding unit.
- EP-ROM was newly added as a service part.***

Reason:

- To ensure this symptom does not occur.
- Requests were received from the field.



B6605548



B6605510

Reissued: 18-Jun-08

Model: <i>Z-folding Unit ZF4000</i>	Date: 16-Apr-08	No.: MB660A02a
--------------------------------------------	-----------------	----------------

MB Reissue

 The items in ***bold italics*** were corrected or added.

Modified Article: PCB –Main Control		Prepared by: S. Ishizu	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for	<input type="checkbox"/> Parts catalog correction	<input type="checkbox"/> Vendor change	<input checked="" type="checkbox"/> Other
Modification:	<input type="checkbox"/> To facilitate assembly	<input type="checkbox"/> To improve reliability	<input type="checkbox"/> To meet standards
	<input type="checkbox"/> Part standardization	<input type="checkbox"/> Product Safety	()

Old part number	New part number	Description	Int	Page	Index	Note
B6605545	B6605547	PCB –Main Control	O/O	23	9	

Change: The PCB software was modified.

Reason: Standardization with the new model.

Model: Z-folding Unit ZF4000	Date: 22-Dec-08	No.: MB660A04
------------------------------	-----------------	---------------

Modified Article: PCB Main Control		Prepared by: H.Matsui	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction	<input type="checkbox"/> Vendor change	<input type="checkbox"/> Other
	<input type="checkbox"/> To facilitate assembly	<input checked="" type="checkbox"/> To improve reliability	<input type="checkbox"/> To meet standards
	<input type="checkbox"/> Part standardization	<input type="checkbox"/> Product Safety	()

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B6605548	B6605560	BASE:MAIN CONTROL:PF4147K50 1P:ASS'Y	1-1	X/O	23	9	
B6605510	B6605551	EP-ROM	1-1	X/O	23	37	

Change: The firmware in the EP-ROM was changed.

Reason: To apply the following changes:

- Symptom corrected: "Copying" is still displayed after a front door open jam occurs.
- Other change: The sending of the paper size code was changed.



Part Change Information List

Date: October 30, 2009

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
Z-folding Unit ZF4000	B660	200910		B6605548	B6605560	BASE:MAIN CONTROL:PF4147K501P:ASS'Y	1	1	X/O		23	9			Y		V0803894	
Z-folding Unit ZF4000	B660	200910		B6605522	B6605523	PCB SUB	1	1	X/O		15	9			Y		T0602648	



Part Change Information List

Date: September 30, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
B-C2/MT-C2 Z-folding Unit	B660	201009		B6605560	B6605561	BASE:MAIN CONTROL:PF4147K501R:ASS'Y	1	1	X/O		15	9					V1001147	10050363



RICOH**Part Change Information List**

Date: April 28, 2011

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
B-C2/MT-C2 Z-folding Unit	B660	201104		B6604146	B6604152	BRACKET:COUPLING:FIN:REAR:PF4147P406	1	1	X/O		3	30					V1002651	10100231



Part Change Information List

Date: June 5, 2017

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
B-C2_MT-C2 Z-folding Unit	B660	201705		B6605451	B6605452	ENTRANCE SENSOR:NO.2:PF4183K631	2	2	O/O	N	11	35					V1603966	16120364



Part Change Information List

Date: November 2, 2017

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
B-C2_MT-C2 Z-folding Unit	B660	201710		11500373	11500438	POWER SUPPLY CODE:AC125V:15A:NA	1	1	O/O	N	3	103					V1701738	