

=====
*** Basic Information ***
=====

[Create date] 2019/05/17

[Program Name] System

[Version] 1.05

[PCB No.]

[Interchangeability] X / O

[Other Firmware Requirements] Exist

[PCB Requirements] None

[Software category] Normal Release

[Release category] Normal Release

[Program category] Firmware

Exported to(language) GEN(all)

[Firmware No.] M0BY5415F

[File Information]

File Name M0BY5415F.fwu

File Type Module for Service

Size 254.00 MB (266340668 byte)

[File Information]

File Name M0BY5415F.rfu

File Type Module for Remote Upgrade

Size 254.01 MB (266346752 byte)

[File Information]

File Name M0BY5415F.zip

File Type Module for Service(Over 1GByte File .zip/.exe)

Size 302.27 MB (316953309 byte)

Check Sum -8Bit Sum: 5107

-16Bit Sum(Little Endian): 0742

-16Bit Sum(Big Endian): 50C5

[Availability of RFU] No

[Production reflection]

=====
*** Note ***
=====

[Note]

=====
*** Important Notes ***
=====

[Important Notes]

=====
*** Modification History ***
=====

[Modifications made:]
Rank C

Version 1.05 Release

[Modification history]

Version 1.04
Rank D

1st Mass production

=====
*** Basic Information ***
=====

[Create date] 2019/05/17

[Program Name] Engine

[Version] 1.051:01

[PCB No.]

[Interchangeability] X / O

[Other Firmware Requirements] None

[PCB Requirements] None

[Software category] Normal Release

[Release category] Normal Release

[Program category] Firmware

Exported to(language) GEN(all)

[Firmware No.] M0BY5420F

[File Information]

File Name M0BY5420F.fwu

File Type Module for Service

Size 15.88 MB (16646644 byte)

[File Information]

File Name M0BY5420F.rfu

File Type Module for Remote Upgrade

Size 15.88 MB (16654592 byte)

[Availability of RFU] Yes

[Production reflection] 2019/04

=====
*** Note ***
=====

[Note]

=====
*** Important Notes ***
=====

[Important Notes]

=====
*** Modification History ***
=====

=====
[Modifications made:]

Rank C

Symptom corrected:

- It may take a long time until printing starts after all heaters reach the setting temperature.
- Paper jam (Jam code:042) may occur due to media floating after resuming printing.
- SC211-02 may occur due to the carriage unit clash to left end.
- Cleaagning cartridge may be recognized as end even though the web remains a little.
- Test print may not start if test print is performed while "Drying" status.

Other changes:

- It may take a long time to warm up the cure heater if a job is sent when all heaters have reached the setting temperature.
- Add an adjustment value register and retrieve function of media feed adjustment and drop position adjustment.

[Modification history]

Version 1.04:01

Rank D

1st Mass production