

<b>Model:</b> PRIPORT EG/EGLT		<b>Date:</b> 30-Sep-03	<b>No:</b> R-C607-001
<b>Subject:</b> EarlGrey-LT firmware history		<b>Prepared by:</b> A. Yoshida, Priport Service Planning Section	
<b>Classification:</b>	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Other (       )	<input checked="" type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information
<b>Model Name:</b> EG (EarlGrey):        Printer unit type 80 RCP80 EGLT (EarlGrey-LT):    Printer unit type 40 RCP40			

Note that this issue is related to the EarlGrey-LT only.

The following is the firmware modification history of Priport product EarlGrey-LT.

## FIRMWARE MODIFICATION HISTORY

Firmware Version	File Name	C.SUM	Production
1.1.7	C6245111D.bin	17AD	From the start of mass-production

**Model:** PRIPORT EG/EGLT**Date:** 30-Sep-03**No:** R-C607-001

Symptom Corrected / Changes	Version
First mass production release.	1.1.7

<b>Model:</b> PRIPORT EG/EGLT		<b>Date:</b> 5-Nov-03	<b>No:</b> R-C607-002
<b>Subject:</b> ROM History (Network Interface Board)		<b>Prepared by:</b> M. Ohtsubo, Priport Service Planning Section	
<b>Classification:</b>	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Other (       )	<input type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input checked="" type="checkbox"/> Retrofit information
<b>Model Name:</b> EG (EarlGrey):        Printer unit type 80 RCP80 EGLT (EarlGrey-LT):    Printer unit type 40 RCP40			

This RTB details the firmware history for the Eland 99 (Network Interface Board).

The software versions listed below can be used for the NIBs on the following models:

Product Name	Product Code for Controller
EG (EarlGrey)	C607
EGLT (EarlGrey-LT)	C624

## FIRMWARE MODIFICATION HISTORY

Firmware Version	File Name	C. SUM	Production
4.1.0	G6785839P.bin	F0A3	From the start of mass-production

**Model:** PRIPORT EG/EGLT**Date:** 5-Nov-03**No:** R-C607-**002**

Symptom Corrected / Changes	Version
First mass production release.	4.1.0

<b>Model:</b> PRIPORT EG/EGLT		<b>Date:</b> 5-Nov-03	<b>No:</b> R-C607-003
<b>Subject:</b> EarlGrey firmware history		<b>Prepared by:</b> M. Ohtsubo, Priport Service Planning Section	
<b>Classification:</b>	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Other (      )	<input type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input checked="" type="checkbox"/> Retrofit information
<b>Model Name:</b> EG (EarlGrey):          Printer unit type 80 RCP80 EGLT (EarlGrey-LT):    Printer unit type 40 RCP40			

This RTB details the system firmware history for the EG (EarlGrey).

## FIRMWARE MODIFICATION HISTORY

Firmware Version	File Name	C. SUM	Production
1.3.0	C6075131E.bin	7ECD	F1620400024
1.2.5	C6075131C.bin	959E	From the start of mass-production

**Model:** PRIPORT EG/EGLT**Date:** 5-Nov-03**No:** R-C607-**003**

Symptom Corrected / Changes	Version
(Modified for use on the Japan model)	1.3.0
First mass production release.	1.2.5

Reissued: 24-Apr-07

<b>Model:</b> PRIPORT EG/EGLT		<b>Date:</b> 30-Sep-03	<b>No:</b> R-C607-001a
<b>Subject:</b> EarlGrey-LT firmware history		<b>Prepared by:</b> M. Kanomata, Priport Service Planning Section	
<b>Classification:</b>	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Part information <input type="checkbox"/> Action required <input type="checkbox"/> Mechanical <input type="checkbox"/> Electrical <input type="checkbox"/> Service manual revision <input type="checkbox"/> Paper path <input type="checkbox"/> Transmit/receive <input type="checkbox"/> Retrofit information <input checked="" type="checkbox"/> Other (      )		
<b>Model Name:</b>			
EG (EarlGrey):      Printer unit type 80 RCP80			
EGLT (EarlGrey-LT):      Printer unit type 40 RCP40			

Note that this issue is related to the EarlGrey-LT only.

The following is the firmware modification history of Priport product EarlGrey-LT.

## FIRMWARE MODIFICATION HISTORY

Firmware Version	File Name	C.SUM	Production
1.1.7	C6245111D.bin	17AD	From the start of mass-production
1.1.9	C6245111E.bin	6194	December 2003 production
1.2.0	C6245111F.bin	EDD8	February 2004 production
1.2.1	C6245111G.bin	BA78	April 2004 production
1.2.5	C6245111H.bin	1D07	September 2004 production
1.2.6	C6245111J.bin	B5BD	September 2006 production
1.2.7	C6245111K.bin	B0BC	January 2007 production

**Note:** File name suffix I has been skipped.

Parts numbers change (C6245111-> **C6245113**)

Symptom Corrected / Changes	Version
First mass production release.	1.1.7
(Minor changes applied for the Japan model).	1.1.9
(Minor changes applied for the Japan model).	1.2.0
(Minor changes applied for the Japan model).	1.2.1
(Minor changes applied for the Japan model).	1.2.5
(Minor changes applied for the Japan model).	1.2.6
(Minor changes applied for the Japan model).	1.2.7

Reissued: 24-Apr-07

<b>Model:</b> PRIPORT EG/EGLT	<b>Date:</b> 30-Sep-03	<b>No:</b> R-C607-001a
-------------------------------	------------------------	------------------------

Firmware Version	File Name	C.SUM	Production
2.0.0	C6245113.bin	4CBD	May 2007 production

Symptom Corrected / Changes	Version
<p><b>Other changes:</b> <b>Supports the HP4-R2.</b></p> <p><b>Note:</b></p> <ol style="list-style-type: none"><li><b><i>If you install ver1.2.7 or older on an HP4-R2 mainframe with an EGLT installed, you will not be able to use User Tools or the printer controller SP modes.</i></b></li><li><b><i>Ver1.2.7 and older are for the Japan model only.</i></b></li></ol>	2.0.0



<b>Model:</b> PRIPORT EG/EGLT		<b>Date:</b> 2-Oct-07	<b>No:</b> R-C607-004
<b>Subject:</b> Service manual revision		<b>Prepared by:</b> M. Kanomata, Priport Service Planning Section	
<b>Classification:</b>	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Other (      )	<input type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive	<input type="checkbox"/> Action required <input checked="" type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information
<b>Model Name:</b> EG (EarlGrey):          Printer unit type 80 RCP80 EGLT (EarlGrey-LT):    Printer unit type 40 RCP40			

Note that this issue is related to the EGLT only.

The EGLT supports the HP4-R2 (#C264), so change your EGLT Service Manuals as follows.  
 The areas in **red/bold** were changed.

-----