

=====  
\*\*\* Basic Information \*\*\*  
=====

[Create date] 2018/10/17

-----  
[Program Name] SYSTEM:SOL-2.5

-----  
[Version] 10040903-1012

-----  
[PCB No.]

-----  
[Interchangeability] X / O

-----  
[Other Firmware Requirements] None

-----  
[PCB Requirements] None

-----  
[Software category] Normal Release

-----  
[Release category] Normal Release

-----  
[Program category] Firmware

-----  
Exported to(language) GEN(all)

[Firmware No.] Y0A25974M

[File Information]

File Name        Y0A25974M.sfw

File Type        Module for Service and Machine Trigger Upgrade(.sfw)

Size             54.58 MB ( 57226348 byte )

[Availability of RFU] No

-----  
[Production reflection] 2018/11

=====  
\*\*\* Note \*\*\*  
=====

[Note]

=====  
\*\*\* Important Notes \*\*\*  
=====

[Important Notes]

=====  
\*\*\* Modification History \*\*\*  
=====

[Modifications made:]

Rank C

1)Additional Model Information

None.

2)Specification Changes

- WPA2 KRACKs vulnerability fixed.

3)Fix

- Image distortion may occurs on irregular JPEG resolution.

F/W versions:

MAIN:1004090300

NETWORK:101200

SYSTEM:10040903-1012

---

[Modification history]

---

Version 10040903-1010

1) Additional Model Information

None.

2) Specification Changes

Fan control changed for preventing mercury bridge.

3) Fix

None.

---

Version 10030903-1010

1) Additional model information

None.

2) Specification changes

None.

3) Fixes

- When multi-byte characters are used in the wireless LAN SSID, connections cannot be made in infrastructure mode.
- A warning will be displayed when Web Image Monitor is used in Safari 10.
- Network errors may occur if the device power is turned on and off repeatedly.

---

Version 10030903-1005

1) Additional Model Information

None.

2) Specification Changes

Display specification of some messages were changed.

3) Fix

None.

-----  
Version 10020903-1005

1) Additional Model Information:  
None.

2) Changes:  
Corresponds to the EU ErP directive Lot 6 criteria, which will be in effect as of January 1, 2017.

3) Fixes:  
None.

Firmware versions:  
- MAIN: 1002090300  
- NETWORK: 100500  
- SYSTEM: 10020903-1005

-----  
Version 10010903-1004

1) Additional Model Information  
None.

2) Specification Changes  
None.

3) Fix  
Projector does not turn on at the designated time set for the power timer.

Remarks:  
F/W version  
MAIN: 1001090300  
NETWORK: 100400  
SYSTEM: 10010903-1004

-----  
Version 10000903-1004

1) Additional Model Information  
None.

2) Changes  
Support for Smart Device Connector's "Connect with QR code" function has been added.  
\*Please change the input to "Network PC" when using it.

3) Fixes  
- Rarely, the projector will display "Please wait" and then freeze when powered on.  
- Movie replays will freeze or be delayed when run via Miracast from some smartphone models.  
- The screen will freeze when projecting from some smartphone models via Miracast.

Remarks  
F/W versions:

- MAIN:1000090300
- NETWORK:100400
- SYSTEM:10000903-1004

-----  
Version 10000903-1002

1) Additional Model Information

None

2) Changes

None

3) Fixes

- It may take a long time to project the next movie when using DLNA compliant hardware.
- The projector may be inoperable when setting the network configuration.

Remarks(FW version)

MAIN: 1000090300

NETWORK: 100200

SYSTEM: 10000903-1002

-----  
Version 10000903-1001

Initial Release

Remarks:

F/W version

Main: 1000090300

NETWORK: 100100

System: 10000903-1001

=====  
\*\*\* Basic Information \*\*\*  
=====

[Create date] 2017/10/31  
-----

[Program Name] Main:SOL-2.5  
-----

[Version] 1004090300  
-----

[PCB No.]  
-----

[Interchangeability] X / O  
-----

[Other Firmware Requirements] None  
-----

[PCB Requirements] None  
-----

[Software category] Normal Release  
-----

[Release category] Normal Release  
-----

[Program category] Firmware  
-----

Exported to(language) GEN(all)

[Firmware No.] Y0A15951E

[File Information]

File Name        Y0A15951E.exe

File Type        Module for Service

Size             1.24 MB ( 1298160 byte )

Check Sum -8Bit Sum: C82B

                 -16Bit Sum(Little Endian): 5653

                 -16Bit Sum(Big Endian): 9CD8

[Availability of RFU] No  
-----

[Production reflection] 2017/11  
-----

=====  
\*\*\* Note \*\*\*  
=====

[Note]  
-----

=====  
\*\*\* Important Notes \*\*\*  
=====

[Important Notes]  
-----

=====  
\*\*\* Modification History \*\*\*  
=====

[Modifications made:]

1) Additional Model Information

None.

2) Specification Changes

Fan control changed for preventing mercury bridge.

3) Fix

None.

-----  
[Modification history]  
-----

Version 1003090300

1) Additional Model Information

None.

2) Specification Changes

Display specification of some messages were changed.

3) Fix

None.

-----  
Version 1002090300

1) Additional Model Information

None.

2) Specification Changes

None.

3) Fix

Miner bug fixed.

-----  
Version 1001090300

1) Additional Model Information

None.

2) Specification Changes

None.

3) Fix

Projector does not turn on at the designated time set for the power timer.

-----  
Version V1000090300  
Initial Release