Technical Bulletin

PAGE: 1/2

Reissued: 12-Apr-16

Model: Soleil-PJ1a/Soleil-PJ1b/Soleil-PJ2/	Date: 19-Oct-12	No.: RY011003f
Altair-PJ1/ Altair-PJ2/Soleil-PJ2.5		

RTB Reissue

The items in bold italics have been corrected.

Subject: Firmware Release Note: Backup Tool		Prepared by: A. Iwaori	
From: VC Products Support Sec., Solution Support Dept.			
Classification:	☐ Troubleshooting	Part information	☐ Action required
	☐ Mechanical	☐ Electrical	☐ Service manual revision
	☐ Paper path	☐ Transmit/receive	☐ Retrofit information
	☐ Product Safety	Other (Firmware)	∑ Tier 2

This RTB has been issued to announce the firmware release information for the **Backup** Tool.

Version	Program No.	Effective Date	Availability of RFU
1.7.0.0	Y0119100G	-	Not available
1.6.0.0	Y0119100F	-	Not available
1.5.0.0	Y0119100E	-	Not available
1.4.0.0	Y0119100D	-	Not available
1.3.0.0	Y0119100C	-	Not available
1.2.0.0	Y0119100B	-	Not available
1.1.0.0	Y0119100A	-	Not available

Note: Definition of Availability of RFU via @Remote

Version	Modified Points or Symptom Corrected
1.7.0.0	1) Additional Model Information None.
	2) Specification Changes Able to obtain and display logs related to mercury bridge.
	3) Error Corrections None.
1.6.0.0	Additional Model Information The following projector is now supported: Soleil PJ2.5
	2) Specification Changes None.
	3) Error Corrections None.
1.5.0.0	Additional Model Information: - Altair PJ2 models have been added.
	Specification Changes: The following functions have been added or changed for Altair PJ2:

[&]quot;Available": The firmware can be updated via RFU or SD card. "Not available": The firmware can only be updated via SD card.

Technical Bulletin

PAGE: 2/2

Reissued: 12-Apr-16

Model: Soleil-PJ1a/Soleil-PJ1b/Soleil-PJ2/	Date: 19-Oct-12	No.: RY011003f
Altair-PJ1/ Altair-PJ2/Soleil-PJ2.5		

Version	Modified Points or Symptom Corrected
	- Added functionality for obtaining service status information (Service Status Tool).
	- The tool automatically changes the projector's "Eco mode" settings to "Active stand-by mode" so that the tool can be executed without changing the setting in advance.
1.4.0.0	Additional Supported Model: Soleil-PJ2
1.3.0.0	Specification Change: Supports the Backup and Restore functions on the following versions of Altair-PJ1 firmware: Main: Ver. 1008220400 Network USB: Ver. 101300 ECO IO: Ver. 101400
1.2.0.0	Additional Model Information: Support for the Altair-PJ1 was added.
1.1.0.0	Initial release



Technical Bulletin

PAGE: 1/1

Reissued: 27-Jan-16

Model: Soleil-PJ1a/ Soleil-PJ1b/ Soleil-PJ2/	Date: 21-Jul-12	No.: RY011004c
Soleil-PJ2.5/Altair-PJ1/ Altair-PJ2		

RTB Reissue

The items in bold italics have been corrected or added.

Subject: Firmware Release Note: USB to UART Bridge Virtual COM Port driver		Prepared by: A. Iwaori	
From: VC Products Support Sec., Solution Support Dept.			
Classification:	Troubleshooting	☐ Part information	☐ Action required
		☐ Electrical	☐ Service manual revision
	☐ Paper path	☐ Transmit/receive	☐ Retrofit information
	☐ Product Safety	Other (Driver)	☑ Tier 2

This RTB has been issued to announce the firmware release information for the **USB to UART Bridge Virtual COM Port driver.**

Version	Program No.	Effective Date	Availability of RFU
1.0.0.0	Y0119102	1	Not available

Note: Definition of Availability of RFU via @Remote

[&]quot;Not available": The firmware can only be updated via SD card.

Version	Modified Points or Symptom Corrected
1.0.0.0	[Modifications made:]
	2015/02/02
	Additional support for Altair PJ2 has been included. No other changes
	have been made to the application.
	2016/01/20
	Additional support for Soleil PJ2.5 has been included. No other changes
	have been made to the application.
	Initial Release

[&]quot;Available": The firmware can be updated via RFU or SD card.

Technical Bulletin

PAGE: 1/1

Model: Altair-PJ1/Altair-PJ2/Soleil-PJ1b/ Date: Soleil-PJ2/Soleil-PJ2.5	27-Jan-16 No.: RY	011008

Subject: Firmware Release Note: QuickPack		Prepared by: A. Iwaori	
From: VC Products Support Sec., Solution Support Dept.			
Classification:	Troubleshooting	☐ Part information	☐ Action required
	☐ Mechanical	☐ Electrical	☐ Service manual revision
	☐ Paper path	☐ Transmit/receive	☐ Retrofit information
	☐ Product Safety	Other (Firmware)	☑ Tier 2

This RTB has been issued to announce the firmware release information for the QuickPack.

Version	Program No.	Effective Date	Availability of RFU
1001	PJSQPA_1001	-	Not available

Note: Definition of Availability of RFU via @Remote "Available": The firmware can be updated via RFU or SD card. "Not available": The firmware can only be updated via SD card.

Version	Modified Points or Symptom Corrected
1001	Additional model information: Initial release.
	2) Specification changes: None.
	3) Error corrections: None.
	Remarks: QuickPack (Win. / Mac.) has been released via the following files.
	[Windows] QuickPack_WIN_V1000.zip Version: v1.0.0.0
	[Macintosh] QuickPack_MAC_V1102.zip Version: v1.1.0.2

Technical Bulletin

PAGE: 1/1

Reissued: 27-Jan-16

Model: Altair-PJ1/ Altair-PJ2/Soleil-PJ2/Soleil-PJ2.5	Date: 05-Feb-13	No.: RY024001c
---	-----------------	----------------

RTB Reissue

The items in **bold italics** have been corrected or added.

Subject: Release Note: FW Update			Prepared by: A. Iwaori
From: VC Products Support Sec., Solution Support Dept.			
Classification:	Troubleshooting	Part information	•
	☐ Mechanical	☐ Electrical	Service manual revision
	☐ Paper path	☐ Transmit/receiv	e Retrofit information
	☐ Product Safety	⊠ Other (Firmwar	e) 🛚 🖂 Tier 2

This RTB has been issued to announce the firmware FW Update Tool.

Version	Program No.	Effective Date	Availability of RFU
1.3.0.0	Y0249101B	February 2015 production	Not available
1.1.0.0	Y0249101A	October 2013 production	Not available
1.0.0.0	Y0249101	Initial release	Not available

Note: Definition of Availability of RFU via @Remote

[&]quot;Not available": The firmware can only be updated via SD card.

Version	Modified Points or Symptom Corrected	
1.3.0.0	Additional Supported Model:	
	Altair-PJ2	
	Soleil-PJ2.5	
1.1.0.0	Additional Supported Model:	
	Soleil-PJ2	
1.0.0.0	This is a tool for updating the firmware for the main board on the following models only: Altair-PJ1	
	Important: This update tool can only be used on these models.	

[&]quot;Available": The firmware can be updated via RFU or SD card.

Model: Soleil-PJ2.5 Date: 30-May-16 No.: RY0A1003 Subject: Service manual revision: Keystone Calibration & Prepared by: Takuma. Troubleshooting Sakakibara From: VC Tech Service Sect., MFP/Printer Tech Service Dept. Troubleshooting ☐ Part information Action required Classification: Mechanical ☐ Electrical ⊠ Service manual revision ☐ Transmit/receive Retrofit information ☐ Paper path **Product Safety** Other () Tier 2

Field Service Manual correction:


3. Replacement and Adjustment

- Keystone Calibration

Step 4.


4. Keep the projector at 20 degrees.

When the adjustment is successfully completed, the values changes from the default [0-0-2048]. (Example: See below)



Wrong


4. Keep the projector at -30 degrees after removing the stand in the front of projector.



Correct

Step 7.


7. Keep the projector at -20 degrees after removing the stand in the front of projector.



Wrong

7. Keep the projector at 30 degrees.

When the adjustment is successfully completed, the values changes from the default [0-0-2048]. (Example: See below)



[A] 30 degrees

Correct


Technical Bulletin

PAGE: 2/3

Model: **Soleil-PJ2.5** Date: 30-May-16 No.: RY0A1003

5. Troubleshooting

Error ID	Status / LED display	Cause	Solution
1	Status The lamp does not turn on correctly. LED display [A] [B] y033t5530 [A] Lamp [B] Temp	The lamp temperature is high.	Wait for the projector to cool down.
		Mercury- bridge*1-has- occurred.	Apply vibration to the lamp unit by shaking it 5 times side to side about 30 cm across. (Lamp Unit 31)
		If the problem persists after you perform the procedure above, replace the parts as described below in the order of appearance.	
		Lamp defect / failure / life expired	Replace the lamp. (<u>Lamp Unit</u> 元)
		Ballast defect /	Replace the ballast. (<u>Lamp Ballast</u>
		PSU defect / failure	Replace the PSU. (<u>PSU</u> 📆)
		Main board defect	Replace the main board. (Main Board 37)





Technical Bulletin

PAGE: 3/3

Model: Soleil-PJ2.5 Date: 30-May-16 No.: RY0A1003 Clean the intake / exhaust section and wait for the projector to cool down. Status Reconsider the The lamp turned off or installation location. stand-by during use, or (Avoid installing the The PSU does not turn on. projector inside a temperature or small, closed box, or at the AC power [LED display a place where the supply voltage None projector intakes the is abnormal. Flashing (The interval exhaust air from depends on stand-by another projector, etc.) settings) • Check the AC power supply. • Replace the PSU. (PSU **;**