*** Basic Information *** [Create date] 2018/02/14 [Program Name] Engine [Version] 1.02.020A [PCB No.] [Interchangeability] X / O [Other Firmware Requirements] None
[Program Name] Engine [Version] 1.02.020A [PCB No.] [Interchangeability] X / O
[Version] 1.02.020A[PCB No.][Interchangeability] X / O
[Version] 1.02.020A[PCB No.][Interchangeability] X / O
[PCB No.] [Interchangeability] X / O
[Other Firmware Requirements] None
•
[PCB Requirements] None
[Software category] Normal Release
[Release category] Normal Release
[Program category] Firmware
Exported to(language) GEN(all) [Firmware No.] Y0155510A [File Information] File Name Y0155510A.exe File Type Module for Service Size 8.46 MB (8870410 byte) Check Sum -8Bit Sum: ED47 -16Bit Sum(Little Endian): 0BD8 -16Bit Sum(Big Endian): 286F [Availability of RFU] No
[Production reflection]
*** Note ***
[Note]
*** Important Notes ***
[Important Notes]

** Modification History ***
Modifications made:]
pecification Change: ris error processing at initialization was changed.
Modification history]

Version 1.02

Symptom Corrected:

Temperature error may occur if any of the following conditions is kept for a while:

- Closing the lens cover

- AV mute

- No Signal (with black background selected)