

=====
*** Basic Information ***
=====

[Create date] 2018/07/27

[Program Name] Booklet Finsher SR3220

[Version] 01.070:04

[PCB No.] D3B95100L

[Interchangeability] X / O

[Other Firmware Requirements] None

[PCB Requirements] None

[Software category] Normal Release

[Release category] Normal Release

[Program category] Firmware

Exported to(language) GEN(all)

[Firmware No.] D3B95300J

[File Information]

File Name D3B95300J.fwu

File Type Module for Service

Size 0.38 MB (394044 byte)

[Availability of RFU] No

[Production reflection] 2017/06

=====
*** Note ***
=====

[Note]

=====
*** Important Notes ***
=====

[Important Notes]

=====
*** Modification History ***
=====

=====
[Modifications made:]

Rank C

Symptom corrected:

- The paper might get stuck between the Paper Guide and the Shift Tray.
- The Transfer Roller might continue to rotate after JAM 360 occurs.

[Modification history]

Version 01.070:04

Symptom corrected:

- Paper may get caught between the paper guide and the shift tray.
- If JAM 360 (Horizontal Path Exit Sensor) occurs, the transfer motor may not stop and continue to rotate.

Version 01.060:04

Symptom corrected:

Minor bug correction (for the production line)

Version 01.050:04

Symptom corrected:

The staple on the booklet is bent, because the stapler does not activate at the correct timing.

Version 01.040:04

Symptom corrected:

For MP C6004, Jam249 may occur when printing in staple mode on custom size paper.

Version 01.030:04

Error corrected:

If the front door is opened and closed, the paper exit motor continues to rotate.

Version 01.020:04

1st Mass production

