# RICOH

# **M**odification **B**ulletin

| Model: Adonis-C1 Scanner Option | Date: 15-Mar-00 | No.: MB359001 |
|---|---|---|

| Modified Article: Keytop - Printer/Scanner | Prepared by: K. Takagi |
|---|---|
| From: Technical Services Dept., GTS Division | |

| Reason for Modification: | ☒ Parts catalog correction | ☐ Vendor change | ☐ To meet standards ( ) |
|---|---|---|---|
| | ☐ To facilitate assembly | ☐ To improve reliability | |
| | ☐ Part standardization | ☐ Other | |

| Old part number | New part number | Description | Q'ty | Int | Page | Index | Note |
|---|---|---|---|---|---|---|---|
| B3591545 | B3598462 | Key Assy – Scanner - NA | 1 | - | 3 | 5 | |

B3591545 (previously called the Keytop) contained only the Scanner Key. This part has been changed to B3598462 (Key Assembly), which includes the Scanner Key and Copy Key - NA (A6937211).

| Model: Adonis-C1 (Scanner option) | Date: 14-Mar-01 | No.: MB359002 |
|---|---|---|

| Modified Article: Scanner Controller | Prepared by: S. Tomoe |
|---|---|
| From: Technical Services Dept., GTS Division | |

| Reason for Modification: | ☐ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization | ☐ Vendor change ☐ To improve reliability ☒ Other | ☐ To meet standards ( ) |
|---|---|---|---|

The scanner controller may not connect with some types of hubs at 10 Mbps, depending on the particular hub and scanner NIB combination. To prevent this problem, the scanner controller has been changed.

| Old part number | New part number | Description | Q'ty | Int | Page | Index | Note |
|---|---|---|---|---|---|---|---|
| A8775310 | A8775311 | Scanner Controller | 1-1 | X/O | 3 | 1 | |