# RICOH

# **T**echnical **B**ulletin

| Model: **MT-C5 Finisher SR4060/70** | Date: 17-May -12 | No.: RD611001 |
|---|---|---|

| Subject: Firmware Release Note: MT-C5 Finisher SR4060/70 | | Prepared by: K. Yamamoto |
|---|---|---|
| From: 1st Tech Service Sect., MFP/Printer Tech Service Dept | | |

Classification:
- ☐ Troubleshooting
- ☐ Mechanical
- ☐ Paper path
- ☐ Product Safety
- ☐ Part information
- ☐ Electrical
- ☐ Transmit/receive
- ☒ Other (Firmware)
- ☐ Action required
- ☐ Service manual revision
- ☐ Retrofit information
- ☒ Tier 2

This RTB has been issued to announce the firmware release information for the
**MT-C5 Finisher SR4060/70.**

| Version | Program No. | Effective Date | Availability of RFU |
|---|---|---|---|
| 01.020:10 | D6125300B | 1st Mass production | Available |

**Note: Definition of Availability of RFU via @Remote**
**"Available" The firmware can be updated via RFU or SD card.**
**"Not available": The firmware can only be updated via SD card.**

| Version | Modified Points or Symptom Corrected |
|---|---|
| 01.020:10 | 1st Mass production |

| Model: **MT-C5 Finisher SR4060/4070** | Date: 17-Oct-12 | No.: RD611002 |
|---|---|---|

| Subject: Part Catalog correction- paper feed | Prepared by: M. Yoneda |
|---|---|
| From: 2nd Tech Service Sect., MFP/Printer Tech Service Dept | |

| Classification: | ☐ Troubleshooting | ☒ Part information | ☐ Action required |
|---|---|---|---|
| | ☐ Mechanical | ☐ Electrical | ☐ Service manual revision |
| | ☐ Paper path | ☐ Transmit/receive | ☐ Retrofit information |
| | ☐ Product Safety | ☐ Other ( ) | ☐ Tier 2 |

## 12.Staple Tray 3 (D612)



| Part number | Description | Q'ty | Page | Index | Note |
|---|---|---|---|---|---|
| B7007852 | STAPLER:SERVICE PARTS:ASS'Y | 1 | 25 | 13 | |

| Part number | Description | Q'ty | Page | Index | Note |
|---|---|---|---|---|---|
| B4686411 | Adjusting Pin - Booklet Stapler | 1 | 25 | 14 | |

| Model: **MT-C5 Finisher SR4060/4070** | Date: 17-Oct-12 | No.: RD611002 |
|---|---|---|

**Change:** The picture of the parts catalog has changed based on the components.
      1. The STAPLER:SERVICE PARTS:ASS'Y (Index 13) was divided into two parts.
      2. An adjusting Pin (index 14) was added to the left side of the
        STAPLER:SERVICE  PARTS:ASS'Y (Index 13).
**Reason:** To clarify the quantity of STAPLER:SERVICE PARTS:ASS'Y (Index 13).