RICOH

Technical **B**ulletin

Reissued: 24-Feb-12

Model: Buffer Pass Unit Type 5010 (D548)	Date: 14-Jul-11	No.: RD548001a

RTB Reissue
The items in **bold italics** have been corrected.

Subject: Firmware Release Note: BufferPassUnit	Prepared by: S. Sasaki
From: 1st PP Tech Service Sect., PP Tech Service Dept.	

Classification:	☐ Troubleshooting	☐ Part information	☐ Action required
	☐ Mechanical	☐ Electrical	☐ Service manual revision
	☐ Paper path	☐ Transmit/receive	☐ Retrofit information
	☐ Product Safety	☒ Other (Firmware)	☒ Tier 2

This RTB has been issued to announce the firmware release information for the
BufferPassUnit.

Version	Program No.	Effective Date	Availability of RFU
02.010:09	*D5481702B*	*February 2012 production*	*Not available*
02.000:09	D5481702A	1st Mass production	Not available

Note: Definition of Availability of RFU via @Remote
"Available" The firmware can be updated via RFU or SD card.
"Not available": The firmware can only be updated via SD card.

Version	Modified Points or Symptom Corrected
02.010:09	*Symptom Corrected:* *Jams when feeding paper longer than 614mm.*
02.000:09	1st Mass production