RICOH

# Part Change Information List

Date: June 30, 2009

| Model | Code | PCIL Nr. | PCIL Correction | Old part number | New part number | Description | Old Q'ty | New Q'ty | Int | 3DPC | Page | Index | Set | Set Int | RTB | Note | Ref. Nr. | ECN Nr. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Copy Connector Cable Type 2105 | B328 | 200906 | | G3305700 | G3305720 | PCB:SDRAM-DIMM:64MB:PBF:ASS'Y | 1 | 1 | O/O | | 3 | 4 | | | | | | |

RICOH

# Part Change Information List

Date: December 29, 2009

| Model | Code | PCIL Nr. | PCIL Correction | Old part number | New part number | Description | Old Q'ty | New Q'ty | Int | 3DPC | Page | Index | Set | Set Int | RTB | Note | Ref. Nr. | ECN Nr. |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Bellini-C2 | B070 | 200912 | | B3235660 | B3285661 | PCB: COUPLING: ASSY | 1 | 1 | O/O | | 3 | 3 | | | | RTB070036 | | |