RICOH

Technical Bulletin

Model: Model TH-C1 Fax Option	Date: 19-Jun-07	No.: RB750001

Subject: User Parameter Switch 34	Prepared by: K. Moriizumi
From: 1st Tech. Support Sec. Service Support Dept.	

Classification:	☐ Troubleshooting	☐ Part information	☐ Action required
	☐ Mechanical	☐ Electrical	☒ Service manual revision
	☐ Paper path	☐ Transmit/receive	☐ Retrofit information
	☐ Product Safety	☐ Other ( )	

The Service Manual (Fax) was corrected as follows:

- **Correct** the description for "User Parameter Switch 34".
  (section 4.5 page 4-77):

Incorrect:
6800F2(H) - User parameter switch 34 (SWUSR_22)
Bit 0: SIP server used with IP-Fax 0: Disabled, 1: Enabled
Bit 1: Gatekeeper server used with IP-Fax 0: Disabled, 1: Enabled

Correct:
6800F2(H) - User parameter switch 34 (SWUSR_22)
Bit 0: Gatekeeper server used with IP-Fax 0: Disabled, 1: Enabled
Bit 1: SIP server used with IP-Fax 0: Disabled, 1: Enabled

Model: Model TH-C1 Fax Option	Date: 23-Apr-09	No.: RB750002

Subject: Harness:Connecting:Speaker		Prepared by: H.K.
From: 1st Tech. Support Sec. Service Support Dept.		
Classification:	☐ Troubleshooting ☒ Part information ☐ Action required ☐ Mechanical ☐ Electrical ☐ Service manual revision ☐ Paper path ☐ Transmit/receive ☐ Retrofit information ☐ Product Safety ☐ Other ( ) ☐ Tier 2	

Change/Reason: Index #19 was missing from the following illustration (pg. 2).