RICOH **M**odification **B**ulletin **PAGE: 1/1**

Model: Martini-C1 Printer/Scanner Kit Type 1075	Date: 17-Dec-02	No.: MG338001

Modified Article: Operation Instructions			Prepared by: K. Miura
From: Technical Services sec. Service Planning Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☐ Other	☐ To meet standards ( )

Please correct your Parts Catalog as follows:

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G3388612	G3398609	Operating Instructions - PRN - TWN	1	_	3	8	
G3388613	G3398606	Operating Instructions - PRN - CHN	1	_	3	8	

Printer/Scanner Kit Type 1075



Printer Kit Type 1075



RICOH Modification Bulletin

Model: Martini-C1 Printer/Scanner Kit Type 1075	Date: 25-Dec-02	No.: MG338002

Modified Article: Network Interface Board			Prepared by: K. Miura
From: Technical Services sec. Service Planning Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☐ Other	☐ To meet standards ( )

Please correct your Parts Catalog as follows:

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B0535254	B0535166	Network Interface Board	1	_	3	5	

Printer/Scanner Kit Type 1075



Modification Bulletin

Model: Martini-C1 Printer/Scanner Kit Type 1075	Date: 27-Dec-02	No.: MG338003

Modified Article: Printer/Scanner DIMM			Prepared by: K. Miura
From: Technical Services Sec. Service Planning Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☒ Other	☐ To meet standards ( )

When printing with the PS driver, the Euro currency symbol is not printed out with 112 of the 136 fonts that are stored in the font ROM. To prevent this, the following parts have been changed:

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G3385117	G3385118	Printer/Scanner DIMM	1	X/O	3	2	
G3395117	G3395118	Printer DIMM	1	X/O	3	15	

For the details, please refer to RTB#Rgen011.



Model: Martini-C1 Printer/Scanner Kity Type 1075	Date: 21-May-03	No.: MG338004

Modified Article: Wireless Card			Prepared by: K. Miura
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☒ Vendor change ☐ To improve reliability ☐ Other	☐ To meet standards ( )

The following part has been changed due to a vendor change.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G6285453	G6285461	Wireless Card - US	1	X/X	3	12	
G6285454	G6285462	Wireless Card - EU	1	X/X	3	12	

Note: When installing the new Wireless Card, it is necessary to upgrade the GW controller and NIB/NetFile firmware. For details, please refer to RTB #RB064019 and #RB064030.