Technical Bulletin

Model: Capella-PJ1	Date: 7-Dec-18	No.: RY0B4001

Subject: How to enter the service mode	Prepared by: T. Sakakibara
From: VC Tech Service Sect., MFP/Printer Tech Service Dept.	

Classification:	☐ Troubleshooting	☐ Part information	☐ Action required
	☐ Mechanical	☐ Electrical	☒ Service manual revision
	☐ Paper path	☐ Transmit/receive	☐ Retrofit information
	☐ Product Safety	☐ Other (Firmware)	☐ Tier 2

The method of entering service mode on Page 56 is incorrect.

Wrong: Press Power -> Left -> Right -> MENU key.

Correct: Press Power -> Left -> Left -> MENU key.