```
==================================================================
*** Basic Information ***
==================================================================
[Create date] 2018/12/21
------------------------------------------------------------------
[Program Name] ADF_DF3090
------------------------------------------------------------------
[Version] 01.380:03
------------------------------------------------------------------
[PCB No.]
------------------------------------------------------------------
[Interchangeability] X / O
------------------------------------------------------------------
[Other Firmware Requirements] None
------------------------------------------------------------------
[PCB Requirements] None
------------------------------------------------------------------
[Software category] Normal Release
------------------------------------------------------------------
[Release category] Normal Release
------------------------------------------------------------------
[Program category] Firmware
------------------------------------------------------------------
Exported to(language) GEN(all)
[Firmware No.] D7795300Q
[File Information]
 File Name        D7795300Q.fwu
 File Type        Module for Service
 Size           0.13 MB ( 132216 byte )
[Availability of RFU] No
------------------------------------------------------------------
[Production reflection] 2019/02
------------------------------------------------------------------


==================================================================
*** Note ***
==================================================================
[Note]

------------------------------------------------------------------



==================================================================
*** Important Notes ***
==================================================================
[Important Notes]

------------------------------------------------------------------



==================================================================
*** Modification History ***
==================================================================
[Modifications made:]
Rank C
```

Symptom corrected:
- SC702-03 might occur.


---------------------------------------------------------------------
[Modification history]
-----------------------------------------
Version 01.360:03
Rank D

Other changes:
- A minor change only for the Japanese model.


-----------------------------------------
Version 01.350:03
Rank C

Other changes:
- When the solenoid stays on for five seconds, the system will be
  reset and the solenoid will be turned off.


-----------------------------------------
Version 01.340:03
Rank C

Symptom corrected:
- SC701-08 might occur


-----------------------------------------
Version 01.330:03
Symptom corrected:
- Initial Jam 001 might occur if another document is fed into the
  ADF while a single-sided document is being scanned.



-----------------------------------------
Version 01.320:03
Other changes:
- The ON/OFF timing of the electromagnetic clutch was changed, to
  reduce the load on the drive motor.
- The range of detection of Jam 14: Skew Correction Sensor was
  changed, to reduce the occurrences of the jam.


-----------------------------------------
Version 01.300:03
In the Administrator Tools tab in System Settings, "ADF operation:
Copier/Document Server: Silent Mode" was added as a new option for another model.


-----------------------------------------
Version 01.290:03
Symptom corrected:
- JAM01 or JAM16 may occur when scanning thin originals.
- JAM14 may occur as a result of an unwanted delay in feeding out
  the last sheet of the original.
- Lifting up the ADF during initialization may cause JAM14 in the
  process following the initialization.

-----------------------------------------
Version 01.200:03
Specification Change:
Minor change in the administrative update process; no changes operational wise.


-----------------------------------------
Version 01.130:03
Version number changed for version management purposes (No program changes made).

-----------------------------------------
Version 01.090:02
Symptom corrected:
1. SC620 may occur.

Other changes:
2. Improved accuracy of paper alignment at paper exit.

-----------------------------------------
Version 01.060:02
Symptom corrected:
Supports scanning of A6 sized originals.

-----------------------------------------
Version 01.060:02
Symptom corrected:
Supports scanning of A6 sized originals.

-----------------------------------------
Version 01.050:01
1st Mass production