	ПΠ
(G(0)	╏╏

Modification Bulletin

PAGE: 1/1

Model: Model T-C1	te: 20-Apr-04		No.: MB174001			
Modified Article: Parts Catalog Correction				Prepared by: A.Ishiyama		
From: 1st Technical Support Sec. Service Support Dept.						
Reason for	□ Parts catalog correction	□Vendo	or cha	inge	☐ To m	neet standards
Modification:	☐ To facilitate assembly	☐To improve reliability		()		
	☐Part standardization					
Modification	The new part is available from	n the first	mas	s production	1.	
Schedule						

Please apply the following correction to your Parts Catalogs.

Incorrect Part Number	Correct Part Number	Description	Q'ty	Int	Page	Index	Note
B1749740	B1749744	One Touch Key Sheet -English	1→1	-/-	6	15-1	

	ПΠ
(G(0)	╏╏

Reason for

Modification:

Modification Schedule

Model: Model T-C1

Modification Bulletin

	Date	e: 24-Jun-04	4	No.: MB174002	
arts Catalog Correction		Prepared by: A.Ishiyama			
Support Sec. Service Support	Dept.				
□ Parts catalog correction	□Vendor cha	ange	☐ To m	neet standards	
☐ To facilitate assembly	☐To improve	ereliability	()		
☐Part standardization					
The new part is available from the first mass production.					

PAGE: 1/2

Please add the following to your Parts Catalogs (previously missing).

Note: See the illustration on the next page.


Modified Article: Parts Catalog Correction

From: 1st Technical Support Sec. Service Support Dept.

Incorrect	Correct	Description	Q'ty	Int	Page	Index	Note
Part Number	Part Number						
	B1749745	Solenoid Spring - Duplex	0→1	-/-	16	4	

Model: Model T-C1 Date: 24-Jun-04 No.: MB174002

11. DRIVE ASSEMBLY



Index	Part No.	Q'ty	B174	
No.	i ait iio.	Description		17
1	B1749714	STEPPING MOTOR - M49SP-2K	1	0
2	B1749717	SOLENOID - DUPLEX	1	0
3	B1749720	STEPPING MOTOR - M4PSP-2NK	1	0
4	B1749745	SOLENOID SPRING - DUPLEX	1	0

	ПΠ
(G(0)	間

Reason for

Modification:

Modification Schedule

Model: Model T-C1

Modification Bulletin

	Date: 06-Jun-08			No.: MB174003	
Prepared			by: T.	Shintani	
Dept.					
☐Vendor change			☐ To meet standards		
☐To improve reliability			()		

PAGE: 1/2

Please add the following to your Parts Catalogs (previously missing).

Note: Corresponding illustration on the next page.

Modified Article: Parts Catalog Correction

From: 1st Technical Support Sec. Service Support Dept.

□ Parts catalog correction

☐ To facilitate assembly

☐Part standardization


OLD Part	NEW	Description	Q'ty	Int	Page	Index	Note
Number	Part Number						
-	B1749746	Driver Ass'y	0→1	-/-	16	0	

The new part is available from the first mass production.

PAGE: 2/2

Model: Model T-C1 Date: 06-Jun-05 No.: MB174003

11. DRIVE ASSEMBLY



Index No.	Part No.	Description		B174 17
0	B1749746	DRIVE ASS'Y	1	0
1	B1749714	STEPPING MOTOR - M49SP-2K	1	0
2	B1749717	SOLENOID - DUPLEX	1	0
3	B1749720	STEPPING MOTOR - M4PSP-2NK	1	0
4	B1749745	SOLENOID SPRING - DUPLEX	1	0

RIGOH

Modification Bulletin

PAGE: 1/2

Model: Model T-C1				20-Jun-05	5	No.: MB174004	
Modified Article: Paper End Actuator				Prepared by: A. Ishiyama			
From: 1st Technical Support Sec. Service Support Dept.							
Reason for	□ Parts catalog correction	□Vendor	dor change		☐ To m	neet standards	
Modification:	☐ To facilitate assembly	☐To improve reliability		eliability	()		
	☐Part standardization						
Modification	The new part is available from	m the first m	nass p	production		_	
Schedule							

OLD Part	NEW	Description	Q'ty	Int	Page	Index	Note
Number	Part Number						
-	B1749747	PAPER END ACTUATOR	0→1	-/-	15	7	

Change: This part was added.

Reason: A request was received from the field.

Note: See the illustration on the next page.




Modification **B**ulletin

PAGE: 2/2

Model: Model T-C1 Date: 20-Jun-05 No.: MB174004

10. PICK-UP ASSEMBLY



B174C910.WMF

Index No.	Part No.	Description	Q'ty	B174 17
1	B1749703	TONER SENSOR - TX	1	0
2	B1749704	QUENCHING LAMP	1	0
3	B1749706	LENS - TONER SENSOR	1	0
4	B1749707	PAPER FEED AND END SENSORS	1	0
5	B1749709	RUBBER - PAPER PICK-UP: RIGHT	1	0
6	B1749710	RUBBER - PAPER PICK-UP : LEFT	1	0
7	B1749747	PAPER END ACTUATOR	1	0

Modification Bulletin

PAGE: 1/1


Model: Model T-C	1	Da	ate: 17-Feb-06	No.: MB174005
Modified Article:	Parts Catalog Correction	Prepared by: T. Sh	intani	
From: 1st Tech. St	upport Sec. Service Support Dept.			
Reason for	□ Parts catalog correction □ Vendor		_	
Modification:	☐ To facilitate assembly ☐ To implied To part standardization ☐ Produc		, — ,	et standards)

NEW Part Number	Description	Q'ty	Int	Page	Index	Note
B1749748	MAIN FRAME ASSY	1	-/-	18	0	-

Change: This part was added. **Reason:** A request was received from the field.

Note: See the illustration as follows.

12. MAIN FLAME ASSEMBLY





Modification **B**ulletin

PAGE: 1/1


Model: Model T-C1 Da			ate: 6-Apr-0)6	No.: MB174006	
Modified Article: Parts Catalog Correction				Prepared	by: T. Sh	intani
From: 1st Tech. Support Sec. Service Support Dept.						
Reason for	□ Parts catalog correction	☐ Vendor	cha	ange	Other	
Modification:	☐ To facilitate assembly ☐ To improve			e reliability	☐ To mee	et standards
	☐ Part standardization	☐ Product	Sa	afety	()

Part Number	Description	Q'ty	Page	Index	Note
B1749749	STACKING LEVER	1	11	6	-

Change: This part was added.

Reason: A request was received from the field. **Note:** See the illustration as follows.

6. EXIT ASSEMBLY



Modification:

Modification Bulletin

Model: Model T-C1 D			ate: 11-Oct-06	No.: MB174007
Modified Article:	Parts Catalog Correction	Prepared by: T. Shi	intani	
From: 1st Tech. Su	pport Sec. Service Support Dept.			
	☐ Parts catalog correction ☐ Vendor		•	at atomalouda
Modification:	☐ To facilitate assembly ☐ To impr	OVE	reliability 🔲 To med	ei siandards

PAGE: 1/1

OLD	NEW	Description	Q'ty	Page	Index	Note
Part Number	Part Number	·	-			
B1749750	B1749751	ADF Pick-Up Roller	1	8	27	
D1749730	B1749752	ADF Friction pad	1	8	28	-


☐ Product Safety

Change: This part No. was changed.

☐ Part standardization

Reason: There is a problem at the supplier. Note: See the illustration as follows.

ADF ASSEMBLY



Modification Bulletin

Date: 30-JAN-07	No.: MB174008
-----------------	---------------


PAGE: 1/1

Model: Model T-C1			Da	ate: 30-JAN	N-07	No.: MB17	4008
Modified Article: Parts Catalog Correction					by: T. Sh	intani	
From: 1st Tech. Support Sec. Service Support Dept.							
Reason for	□ Parts catalog correction	☐ Vendor o	cha	ange	Other		
Modification: ☐ To facilitate assembly ☐ To improve ☐ Part standardization ☐ Product Saf		☐ To improve reliability		☐ To mee	et standards		
		fety	()			

NEW	Description	Q'ty	Page	Index	Note
Part Number					
B1747500	GEAR – PICK UP	1	3	24	
B1747501	SHAFT – PICK UP	1	3	25	-

Change: These parts were added. **Reason:** Requests from the field.

1. MAIN ASSEMBLY




Model: Model T-C1 Da			ate: 23-Feb	o-07	No.: MB174009	
Modified Article: Parts Catalog Correction				Prepared	by: T. Sh	intani
From: 1st Tech. Support Sec. Service Support Dept.						
Reason for	□ Parts catalog correction	☐ Vendor	cha	ange	Other	
Modification:	☐ To facilitate assembly	☐ To improve reliability		e reliability	☐ To mee	et standards
	☐ Part standardization ☐ Product Saf			afety	()

NEW Part Number	Description	Q'ty	Page	Index	Note
B1747502	WHITE BAR	1	8	29	-

Change: This part was added. **Reason:** Requests from the field.

3. ADF ASSEMBLY



Modification **B**ulletin


PAGE: 1/1


Model: Model T-C	1	Da	ate: 4-Oct-07	No.: MB174010
Modified Article:	Parts Catalog Correction		Prepared by: T. Sh	intani
From: 1st Tech. S	upport Sec. Service Support Dept.			
Reason for	□ Parts catalog correction □ Vendor	cha	ange	
Modification:	☐ To facilitate assembly ☐ To impr	ove	e reliability 🔲 To me	et standards
	☐ Part standardization ☐ Product	Sa	afety ()

NEW	Description	Q'ty	Page	Index	Note
Part Number					
B1749753	GUIDE – FRONT	1	10	5	-
B1749754	GUIDE – SUB	1	10	6	-
B1749755	GUIDE - REAR	1	10	7	-

Change: These parts were added. Reason: Requests from the field.

5. CASSETTE ASSEMBLY





Modification **B**ulletin


PAGE: 1/1

Model: Model T-C1			Da	ate: 12-Feb	o-08	No.: MB174	011
Modified Article:	Parts Catalog Correction			Prepared	by: T. Shi	intani	
From: 1st Tech. Su	ipport Sec. Service Support [Dept.					
Reason for	□ Parts catalog correction	☐ Vendor o	cha	ange	Other		
Modification:	☐ To facilitate assembly	☐ To improve		e reliability	☐ To me	et standards	
☐ Part standardization ☐ Product S		Sa	afety	()		

NEW Part Number	Description	Q'ty	Page	Index	Note
B1749756	HARNESS - LIU	1	3	26	-

Change: This part was added.
Reason: Requests from the field.

1. MAIN ASSEMBLY



Modification **B**ulletin

	Г	A	J	⊏.	


Model: Model T-C1 Da			ı te : 22-Aug	j-08	No.: MB174012	
Modified Article:		Prepared	by: T. Sh	intani		
From: 1st Tech. Su	ipport Sec. Service Support [Dept.				
Reason for	□ Parts catalog correction	☐ Vendor o	cha	nge	Other	
Modification:	☐ To facilitate assembly	☐ To impro	ove	reliability	☐ To me	et standards
	☐ Part standardization	☐ Product	Saf	fety	()

NEW Part Number	Description	Q'ty	Page	Index	Note
B1749757	ADF MOTOR_GEAR ASSY	1	8	30	-

Change: This part was added. **Reason:** Requests from the field.

3. ADF ASSEMBLY

Rev. 11/30/2006



Modification Bulletin


PAGE: 1/1

Model: Model T-C	1		Da	ate: 26-Aug	J-08	No.: MB174013	3
Modified Article:	Parts Catalog Correction			Prepared	by: T. Shi	intani	
From: 1st Tech. Su	ipport Sec. Service Support D	Dept.					
Reason for	□ Parts catalog correction	☐ Vendor	cha	ange	Other		
Modification: ☐ To facilitate assembly ☐ To improv		ove	e reliability	☐ To mee	et standards		
☐ Part standardization ☐ Product Sa			afety	()		

NEW Part Number	Description	Q'ty	Page	Index	Note
B1749758	HARNESS-INLET	1	3	27	-

Change: This part was added.
Reason: Requests from the field.

1. MAIN ASSEMBLY




Model: Model T-C1			ate: 04-Feb	-09	No.: MB174014	
Modified Article: ADF ASSEMBLY					by: Y.Gar	man
From: 1st Tech. Su	ipport Sec. Service Support [Dept.				
Reason for	□ Parts catalog correction	☐ Vendor o	cha	ange	Other	
Modification:	☐ To facilitate assembly	☐ To impro	ove	ereliability	☐ To mee	et standards
	☐ Part standardization	☐ Product	Sa	afety	()

Change: This part was added.
Reason: Requests from the field.

NEW Part	Description	Q'ty	Int	Page	Index	Note
B1749759	COVER ADF LOWER	1	-	8	31	

3. ADF ASSEMBLY




Modification Bulletin

PAGE: 1/

Model: Model T-0	C1		Date: 16-Fel	b-09	No.: MB174015		
Modified Article	SIDE COVER ASSEMBLY	Prepared	d by: Y.Ga	man			
From: 1st Tech. S	Support Sec. Service Support I	Dept.					
Reason for	□ Parts catalog correction	☐ Vendor c	hange	Other			
Modification:	☐ To facilitate assembly	☐ To impro	ve reliability	☐ To me	eet standards		
	☐ Part standardization	☐ Product S	Safety	()		

Change: This part was added.
Reason: Requests from the field.

NEW Part	Description	Q'ty	Int	Page	Index	Note
B1749760	GUIDE FEED FRAME	1	1	9	10	





Part Change Information List

Date: October 30, 2009

Model	Code PCIL Nr. O	Old part N	w part	Description	Old Q'ty New Q'ty Int 3DPC	Page Index Set	Set Int RTB	Note	Ref. Nr. ECN Nr.
Model	Code PCIL Nr. Correction	number i	ımber	Description	Old Q ty New Q ty IIIt 3DI C	rage index set	Set IIIt 1115	Note	Hel. IVI. LON IVI.
T-C1	B174 200910	G	801152 BUSHING:JC7241364A		0 1	15 8	Y		V0902590



Part Change Information List

Date: November 30, 2009

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q't	y New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
T-C1	B174	200911			B1749762	PICK-UP ASS'Y:JC96-02715B		0	1		15	8			Υ		V0902590	



Part Change Information List

Date: December 29, 2009

Model	Code	PCIL Nr.	PCIL	Old part	New part		Description	Old Q'ty 1	New O'ty	Int	3DPC Page	Index Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
Model	Oode	I OIL IVI.	Correction	number	number		Description	Old Q ty	ivew Q ty	1111	obi o i age	ilidex del	Oct IIIt	шь	Note	riei. IVI.	LOIVIVI.
T-C1	B174	200912		B1749565	B1749800	CCD UNIT	·	1	1	-	6	13				V0701631	