

Model: Model S-F2.6 / S-F2.6L		Date: 5-Mar-07	No.: RH556019
Subject: New Model F-2.6 / S-F2.6L		Prepared by: T. Shintani	
From: Technical Services sec. Service Planning Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Other (      )	<input type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive	<input type="checkbox"/> Action required <input checked="" type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information

Model **S-F2.6** has been newly released. This bulletin shows the differences between this new model and the S-F2.5.

## **Service Manual Information**

### **1. SPECIFICATIONS**

#### **Memory Capacity**

##### **SAF:**

**Standard:** 6MB to 8MB

### **2. OTHER**

#### **Design Changes:**

- The Ricoh logo was updated
- The Energy Star label was changed
- The front panel was redesigned
- The Quick panel was redesigned

#### **Software:**

Officially supports the Cisco Call Manager (CCM).

## **Parts Catalog Information**

A new Parts Catalog was issued for this model. It contains all of the MB P/N changes announced up until the date this RTB was issued.