

Model: Adonis-C4.5		Date: 8-Jun-07	No.: MB296001
Modified Article: EMBLEM - LANIER		Prepared by: K. Takagi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B2966438	-	EMBLEM SHEET – LAN35	1		11	2	
B2976438	-	EMBLEM SHEET – LAN45	1		11	2	

Change: These parts were deleted from service parts.

Reason: There were mistakenly listed in the Parts Catalog.

Model: Adonis-C4.5b/c		Date: 19-Jun-07	No.: MB296002
Modified Article: Parts Catalog Correction_Fusing Unit		Prepared by: K. Takagi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Incorrect P/N	Correct P/N	Description	Q'ty	Page	Index	Note
B1987315	B2987315	Fusing Unit: NA: Service: Assy	1	47	1	
B1987715	B2987715	Fusing Unit: EU: Service: Assy	1	47	1	

Change/Reason: The part numbers were corrected.

Note: The incorrect part numbers are only mentioned on [pg. 120](#).

Model: Adonis-C4.5b/c		Date: 6-Jul-07	No.: MB296003
Modified Article: Parts Catalog Correction_Fusing Unit		Prepared by: K. Takagi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

P/N	Incorrect Description	Correct Description	Q'ty	Page	Index
B2969640	Developer Type 26 Black	Developer Black	-	112	-
B2969640	Developer Type 26 Black	Developer Black	-	121	-

Change/Reason: The part descriptions were corrected.

Note: The description for P/N B2969640 on pg. 109 is correct.

Model: Model A-C4.5		Date: 4-Dec-07	No.: MB296004
Modified Article: HDD		Prepared by: K. Takagi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☒ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B1795995	B2475227	HDD:HITACHI:80GB:PATH2:PA TA	1- 1	O/O	71	16	

Change/Reason: Production was stopped on the older version.

Model: Adonis-C4.5b/c		Date: 10-Dec-07	No.: MB296005
Modified Article: Fusing Unit/Transfer Unit		Prepared by: K. Takagi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Page	Index	Note
	B2987315	Fusing Unit: NA: Service: Assy	0-1	47	*	
	B2987715	Fusing Unit: EU: Service: Assy	0-1	47	*	
	B0049015	Transfer unit	0-1	45	*	

Change: These units were added as service parts.

Reason: A request was received from the field.

Model: Adonis-C4.5		Date: 18-Feb-08	No.: MB296006
Modified Article: PSU		Prepared by: K. Takagi	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☒ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
AZ230186		Power Supply Unit: 285W	1-1	O/O	67	13	
	AZ230217	Power Supply Unit - 120V, 285W					
AZ230187		Power Supply Unit - 285W	1-1	O/O	67	13	
	AZ230218	Power Supply Unit - 230V, 285W					

Change: The shape of the power supply unit was changed.

Reason: The shape of the PSU cooling fan was changed, and the fan is mounted on the PSU.

Model: Adonis-C4.5b/c		Date: 23-Jan-09	No.: MB296007
Modified Article: Development sleeve		Prepared by: K. Hamada	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☒ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B0823100	B0823101	Development sleeve: Ass'y	1-1	X/O	39	4	
B2133010	B2133011	Development Unit	1-1	X/O	39	1	

Change: The surface treatment for the development roller was changed.

Reason: To further ensure that toner cannot stick to the development sleeve.

Model: Adonis-C4.5b/c		Date: 23-Feb-09	No.: MB296008
Modified Article: DIMM: 128MB		Prepared by: S. Tomoe	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☒ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B5845050	B5845051	PCB:DDR-DIMM:128MB	1-1	O/O	71	15	

Change/ Reason: Vendor change



Part Change Information List

Date: March 18, 2009

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number
Adonis-C4.5b/c	B291	200903		A2321257	B2981257	CAP:COVER:UPPER	1	1	O/O		13	14					V0803798
Adonis-C4.5b/c	B295	200903		A2321257	B2981257	CAP:COVER:UPPER	1	1	O/O		13	14					V0803798
Adonis-C4.5b/c	B296	200903		A2321257	B2981257	CAP:COVER:UPPER	1	1	O/O		13	14					V0803798
Adonis-C4.5b/c	B297	200903		A2321257	B2981257	CAP:COVER:UPPER	1	1	O/O		13	14					V0803798
Adonis-C4.5b/c	B291	200903		B1986350	B1986352	OPERATION SUB-UNIT:NA:ASS'Y	1	1	X/O		15	1					V0804330
Adonis-C4.5b/c	B291	200903		B1986362	B1986363	OPERATION SUB-UNIT:EU:ASS'Y	1	1	X/O		15	1					V0804330
Adonis-C4.5b/c	B295	200903		B1986350	B1986352	OPERATION SUB-UNIT:NA:ASS'Y	1	1	X/O		15	1					V0804330
Adonis-C4.5b/c	B295	200903		B1986362	B1986363	OPERATION SUB-UNIT:EU:ASS'Y	1	1	X/O		15	1					V0804330
Adonis-C4.5b/c	B296	200903		B1986350	B1986352	OPERATION SUB-UNIT:NA:ASS'Y	1	1	X/O		15	1					V0804330
Adonis-C4.5b/c	B296	200903		B1986362	B1986363	OPERATION SUB-UNIT:EU:ASS'Y	1	1	X/O		15	1					V0804330
Adonis-C4.5b/c	B296	200903		B1986385	B1986386	OPERATION SUB-UNIT:AA:ASS'Y	1	1	X/O		15	1					V0804330
Adonis-C4.5b/c	B296	200903		B2976380	B2976381	OPERATION SUB-UNIT:KOR:ASS'Y	1	1	X/O		15	1					V0804330
Adonis-C4.5b/c	B297	200903		B1986350	B1986352	OPERATION SUB-UNIT:NA:ASS'Y	1	1	X/O		15	1					V0804330
Adonis-C4.5b/c	B297	200903		B1986362	B1986363	OPERATION SUB-UNIT:EU:ASS'Y	1	1	X/O		15	1					V0804330
Adonis-C4.5b/c	B297	200903		B1986385	B1986386	OPERATION SUB-UNIT:AA:ASS'Y	1	1	X/O		15	1					V0804330
Adonis-C4.5b/c	B297	200903		B2976380	B2976381	OPERATION SUB-UNIT:KOR:ASS'Y	1	1	X/O		15	1					V0804330



Part Change Information List

Date: April 30, 2009

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number
Adonis-C4.5b/c	B291	200904		B2135222	H3106173	TOUCH PANEL:HVGA:FU-ACF	1	1	X/O		3	15					V0804330
Adonis-C4.5b/c	B295	200904		B2135222	H3106173	TOUCH PANEL:HVGA:FU-ACF	1	1	X/O		3	15					V0804330
Adonis-C4.5b/c	B296	200904		B2135222	H3106173	TOUCH PANEL:HVGA:FU-ACF	1	1	X/O		3	15					V0804330
Adonis-C4.5b/c	B297	200904		B2135222	H3106173	TOUCH PANEL:HVGA:FU-ACF	1	1	X/O		3	15					V0804330





Part Change Information List

Date: Jun 30, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
A-C4.5b/c	B291	201006		B2136049	B2136048	PICKUP SOLENOID	1	1	X/O		27	37					V1001108	
A-C4.5b/c	B295	201006		B2136049	B2136048	PICKUP SOLENOID	1	1	X/O		27	37					V1001108	
A-C4.5b/c	B296	201006		B2136049	B2136048	PICKUP SOLENOID	1	1	X/O		27	37					V1001108	
A-C4.5b/c	B297	201006		B2136049	B2136048	PICKUP SOLENOID	1	1	X/O		27	37					V1001108	



Part Change Information List

Date: June 30, 2011

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
A-C4.5	B298	201105		B0822781	D0892781	BRACKET:SENSOR	1	1	X/O		31	40					V1002614	10101257
A-C4.5	B291	201105		B0822781	D0892781	BRACKET:SENSOR	1	1	X/O		31	40					V1002614	10101257
A-C4.5	B295	201105		B0822781	D0892781	BRACKET:SENSOR	1	1	X/O		31	40					V1002614	10101257
A-C4.5	B296	201105		B0822781	D0892781	BRACKET:SENSOR	1	1	X/O		31	40					V1002614	10101257
A-C4.5	B297	201105		B0822781	D0892781	BRACKET:SENSOR	1	1	X/O		31	40					V1002614	10101257



Part Change Information List

Date: September 30, 2011

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
A-C4.5b/c	B291	201109		B1959590	B1959593	NVRAM - ZERO COUNTER	1	1	O/O		71	10					V1002605	
A-C4.5b/c	B295	201109		B1959590	B1959593	NVRAM - ZERO COUNTER	1	1	O/O		71	10					V1002605	
A-C4.5b/c	B296	201109		B1959590	B1959593	NVRAM - ZERO COUNTER	1	1	O/O		71	10					V1002605	
A-C4.5b/c	B297	201109		B1959590	B1959593	NVRAM - ZERO COUNTER	1	1	O/O		71	10					V1002605	



Part Change Information List

Date: November 30, 2011

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
A-C4.5	B291	201111		AX050292	AX050329	DC MOTOR:TONER BOTTLE/ASS'Y	1	1	O/O		61	38					V1002854	
A-C4.5	B295	201111		AX050292	AX050329	DC MOTOR:TONER BOTTLE/ASS'Y	1	1	O/O		61	38					V1002854	
A-C4.5	B296	201111		AX050292	AX050329	DC MOTOR:TONER BOTTLE/ASS'Y	1	1	O/O		61	38					V1002854	
A-C4.5	B297	201111		AX050292	AX050329	DC MOTOR:TONER BOTTLE/ASS'Y	1	1	O/O		61	38					V1002854	
A-C4.5	B298	201111		AX050292	AX050329	DC MOTOR:TONER BOTTLE/ASS'Y	1	1	O/O		61	38					V1002854	



Part Change Information List

Date: January 31, 2012

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
A-C4.5	B295	201201		B0771250	B0776314	COVER:UPPER	1	1	O/O		13	35					V1100089	11010199
A-C4.5	B296	201201		B0771250	B0776314	COVER:UPPER	1	1	O/O		13	35					V1100089	11010199
A-C4.5	B297	201201		B0771250	B0776314	COVER:UPPER	1	1	O/O		13	35					V1100089	11010199
A-C4.5	B298	201201		B0771250	B0776314	COVER:UPPER	1	1	O/O		13	35					V1100089	11010199
A-C4.5	B291	201201		B0771250	B0776314	COVER:UPPER:EU	1	1	O/O		13	35					V1100089	11010199



Part Change Information List

Date: March 30, 2012

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
A-C4.5	B291	201203		B0771305	B0776322	INNER COVER:RIGHT:EU	1	1	O/O		33	9					V1100089	11010199
A-C4.5	B295	201203		B0771305	B0776322	INNER COVER:RIGHT:EU	1	1	O/O		33	9					V1100089	11010199
A-C4.5	B296	201203		B0771305	B0776322	INNER COVER:RIGHT:EU	1	1	O/O		33	9					V1100089	11010199
A-C4.5	B297	201203		B0771305	B0776322	INNER COVER:RIGHT:EU	1	1	O/O		33	9					V1100089	11010199
A-C4.5	B298	201203		B0771305	B0776322	INNER COVER:RIGHT:EU	1	1	O/O		33	9					V1100089	11010199



Part Change Information List

Date: November 30, 2012

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
A-C4.5	B291	201211		AX310046	AX310050	TOTAL COUNTER:7FIG:24V	1	1	O/O		13	28					V1201380	
A-C4.5	B295	201211		AX310046	AX310050	TOTAL COUNTER:7FIG:24V	1	1	O/O		13	28					V1201380	
A-C4.5	B296	201211		AX310046	AX310050	TOTAL COUNTER:7FIG:24V	1	1	O/O		13	28					V1201380	
A-C4.5	B297	201211		AX310046	AX310050	TOTAL COUNTER:7FIG:24V	1	1	O/O		13	28					V1201380	
A-C4.5	B298	201211		AX310046	AX310050	TOTAL COUNTER:7FIG:24V	1	1	O/O		13	28					V1201380	



Part Change Information List

Date: November 2, 2015

[illegible]



Part Change Information List

Date: July 1, 2016

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
A-C4.5b_c	B291	201607		B0771291	B0776328	COVER:REAR:EU	1	1	O/O	N	13	10					V1100089	11010199
A-C4.5b_c	B295	201607		B0771291	B0776328	COVER:REAR:EU	1	1	O/O	N	13	10					V1100089	11010199
A-C4.5b_c	B296	201607		B0771291	B0776328	COVER:REAR:EU	1	1	O/O	N	13	10					V1100089	11010199
A-C4.5b_c	B297	201607		B0771291	B0776328	COVER:REAR:EU	1	1	O/O	N	13	10					V1100089	11010199