

Reissued:21-Aug-06

Model: K-C3	Date: 04-Aug-06	No.: MB245001a
-------------	-----------------	----------------

MB Reissue

The items in bold italics have been corrected or added.

Modified Article: Case:Development Roller:Ass'y		Prepared by: Y.Murata	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction	☐ Vendor change	☐ Other
	☐ To facilitate assembly	☐ To improve reliability	☒ To meet standards (RoHs compliant)
	☐ Part standardization	☐ Product Safety	

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
<i>B0393150</i>	<i>B0393159</i>	Case:Development Roller:Ass'y	1	X/O	35	7	

Change: The materials for these parts were changed.

Reason: To comply with the RoHS Directive.

Note: This change applies to all K series models .

Reissued:21-Aug-06

Model: K-C3 and Great Wall-C1	Date: 7-Aug-06	No.: MB245002b
-------------------------------	----------------	----------------

MB Reissue

The items in bold italics have been corrected or added.

Modified Article: PCU - Ass'y		Prepared by: Y.Murata	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction	☐ Vendor change	☐ Other
	☐ To facilitate assembly	☐ To improve reliability	☒ To meet standards (RoHs compliant)
	☐ Part standardization	☐ Product Safety	

K-C3 (B245/B268/B269/B276/B277)

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B2592200	B2592210	PCU – Ass'y	1	X/O	35	*	

GW-C1 (B282/B283)

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B2592200	B2592210	PCU - Ass'y	1	X/O	29	*	

Change: The materials for these parts were changed.**Reason:** To comply with the RoHS Directive.

Model: K-C3		Date: 22-Aug-06	No.: MB245003
Modified Article: Guide Plate:Paper Feed:Right		Prepared by: Y.Murata	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☒ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B0406067	B2776067	Guide Plate:Paper Feed:Right	1	X/O	31	8	

Change: The shape of part has changed.

Reason: To decrease the number of jams.

Note: This change applies to the models which have a 2nd paper feed section (B269, B277).

Model: K-C2		Date: 23-Aug-06	No.: MB121023
Modified Article: Conformance with new Energy Star regulation		Prepared by: Hiromoto Saitoh	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☐ Product Safety	☐ Other ☒ To meet standards ()

Change: The following part was deleted.

Reason: To conform to the revised Energy Star regulations applied from spring 2007.

Note: This change applies to the following models:

K-C2, K-C2.5, K-C3, PD-C1 (B121, B122, B123, B245, B259, B260, B261, B268, B269, B270, B276, B277)

Old P/N	New P/N	Description	Q'ty	Page	Index	Note
GA003035	-	Energy Decal	1→0	9 11 67	23 28 1	



[RAI (China) Production]

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NO.
RICOH: Aficio 2015 Gestetner: DSm615	110/50,60	Taiwan	B121-19	J9066100021
RICOH: Aficio 2015	220/50,60	China	B121-21	J9066130001
RICOH: Aficio 2015	220/50,60	Korea	B121-28	J9066100001
RICOH: Aficio 2018 Gestetner: DSm618	110/50,60	Taiwan	B122-19	J9166200001
SAVIN: 8016 Gestetner: DSm616 LANIER: LD116 RICOH: Aficio 2016	120/50,60	USA, Central/South America	B259-17	K8166140001
Nashuatec: DSm616 Rex-Rotary: DSm616 Gestetner: DSm616	220/50,60	Europe, Central/South America	B259-22	K8166110001
IS 2216	220/50,60	Europe	B259-26	9N58160001
RICOH: Aficio 2016	220/50,60	Europe, etc.	B259-27	K8166120001
Gestetner: DSm616 LANIER: LD116 RICOH: Aficio 2016	220/50,60	Asia, Pacific	B259-29	K8166150001
SAVIN: 8020 Gestetner: DSm620 LANIER: LD120 RICOH: Aficio 2020	110/50,60	USA, Central/South America	B260-17	K8266140001

Model: K-C2		Date: 23-Aug-06		No.: MB121023
RICOH: Aficio 2020	220/50,60	China	B260-21	K8266100001
Nashuatec: DSm620 Rex-Rotary: DSm620 Gestetner: DSm620	220/50,60	Europe, Central/South America	B260-22	K8266110001
IS 2220	220/50,60	Europe	B260-26	9N68160001
RICOH: Aficio 2020	220/50,60	Europe, etc.	B260-27	K8266120001
Gestetner: DSm620 LANIER: LD120 RICOH: Aficio 2020	220/50,60	Asia, Pacific	B260-29	K8266150001
SAVIN: 8020d Gestetner: DSm620d LANIER: LD120d RICOH: Aficio 2020D	110/50,60	USA, Central/South America	B261-17	K8366140001
Gestetner: DSm 620d RICOH: Aficio 2020D	110/50,60	Taiwan	B261-19	K8366100001
RICOH: Aficio 2020D	220/50,60	China	B261-21	K8366100081
Nashuatec: DSm620d Rex-Rotary: DSm620d Gestetner: DSm620d	220/50,60	Europe, Central/South America	B261-22	K8357211139
LANIER: LD120d	220/50,60	Europe	B261-24	K8366100506
IS 2220D	220/50,60	Europe	B261-26	9N78160001
RICOH: Aficio 2020D	220/50,60	Europe, etc.	B261-27	K8366120001
RICOH: Aficio 2015L	220/50,60	China	B270-21	L2366100001
Infotec: IS 2320	220/50,60	Europe	B277-26	9Y88260001
RICOH: Aficio MP 2000 N/R/G: MP 2000 Lanier: MP 2000	220/50,60	Europe, etc.	B277-27	L7066200001


Model:K-C3		Date: 4-Sep-06	No.: MB245004
Modified Article: PCB Gdi-Basic		Prepared by: Y.Murata	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction	☐ Vendor change	☐ Other
	☐ To facilitate assembly	☐ To improve reliability	☐ To meet standards
	☐ Part standardization	☐ Product Safety	()

Change: Delete LAN interface as below. (Put red X on the illustration)

Reason: There is no LAN interface in PCB GDI-Basic.

Note: This change applies to B268, B269.

Parts Catalog, page 64



Model: GreatWall-C1 and K-C2.5 for Founder		Date: 14-Sep-06	No.: MB121024
Modified Article: P/N Differences: GreatWall-C1 and K-C2.5 for Founder		Prepared by: Y.Murata	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☒ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

For B282-64

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B2821412	B2821413	Operation Sub-Unit:Base :Duplex:Fou:Ass'y	1	X/O	9	4	

For B283-64

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B2831422	B2831423	Operation Sub-Unit:Base :GW-C1:Ass'y	1	X/O	9	4	

For B260-64

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B1211472	B2591472	Sheet:Operation Panel:EU	1	X/O	11	16	

For B261-64

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B1231472	B2611472	Sheet:Operation Panel:Duplex:EU	1	X/O	11	16	

Change: The color of the operation panel sheet was changed for the GreatWall-C1 and Founder model of the K-C2.5.

Reason: To meet OEM needs.

Model: GreatWall-C1		Date: 13-Sep-06	No.: MB245005
Modified Article: Guide Plate		Prepared by: Y.Murata	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☒ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B0434662	B2824662	Guide Plate-Vertical Transport	1	X/O	39	5	
B0392655	B2822655	Guide:Vertical Transport	1	X/O	33	4	

Change: The length of the Mylar attached to the guide plate was decreased.

Reason: To further ensure paper jams do not occur.

Note: This change applies to the B282-21 only.

Model:K-C3 and GreatWall-C1		Date: 13-Sep-06	No.: MB245006
Modified Article: Shaft:Scale		Prepared by: Y.Murata	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☒ To meet standards (RoHs compliant) ☐ Part standardization ☐ Product Safety		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
A1931759	B3901759	Shaft:Scale	1	O/O	11, 15	1	

Change: The material for this part was changed.

Reason: To comply with the RoHs Directive.

Note: This part is on pg. 15 of the Kir-C3 Parts Catalog, and on pg. 11 of the GreatWall-C1 Parts Catalog.

Model:K-C3 and GW-C1		Date: 14-Sep-06	No.: MB245007
Modified Article: Power Supply Unit		Prepared by: Y.Murata	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☒ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
AZ230201	AZ230219	Power Supply Unit-230V	1	X/O	47,53	13	

Change: The vender of this part was changed

Note: This part is on pg. 53 of the Kir-C3 Parts Catalog, and on pg. 47 of the GW-C1 Parts Catalog.


Model: Kir-C3 		Date: 18-Jan-07	No.: MB245009
Modified Article: Reflector		Prepared by: Y. Murata	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction	☐ Vendor change	☐ Other
	☐ To facilitate assembly	☐ To improve reliability	☐ To meet standards (RoHs compliant)
	☐ Part standardization	☐ Product Safety	

Change: The reflectors were deleted.

Reason: The xenon lamps in these products do not need reflectors.

Note: Delete the following illustration.

Pg.16



Model: K-C3		Date: 13-Feb-07	No.: MB245010
Modified Article: PCB BICU		Prepared by: Y. Yoshida	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety		

Incorrect part number	Correct part number	Description	Q'ty	Int	Page	Index	Note
B2765101	B2765106	PCB:BICU:GDI:EXP:ASS'Y	1	X/O	53	9	
B2765103	B2765108	PCB:BICU:GDI:EXP:ASS'Y	1	X/O	53	9	

Change/Reason: The part numbers in the Parts Catalog were corrected.

Model: K-C3 (For Korea only)		Date: 14-May-07	No.: MB245011
Modified Article: PCB BICU		Prepared by : M. Ishihara	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety		

Incorrect part number	Correct part number	Description	Q'ty	Int	Page	Index	Note
-	B2765125	PCB : BICU : KOR : ASS'Y	1		83	*	


Change/Reason: The part number in the Parts Catalog was missing.

Model: K-C3 (Fax Option)		Date: 19-Jun-07	No.: MB245012
Modified Article: Parts Catalog Correction		Prepared by: M. Ishihara	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Please correct your parts catalog as follows.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B8685080	-	PCB : MBU : Ass'y	1	-	2	9→8	
B8685172	-	PCB : GWFCU3 : NA	1	-	2	8→9	
B8685174	-	PCB : GWFCU3 : EU	1	-	2	8→9	

1.Fax Option (B868)




Model: Model K-C3		Date: 21-Jun-07	No.: MB245013
Modified Article: New part number was added		Prepared by: Y.Yoshida	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Change: This part was added.

Reason: Requests were received from the field.

NEW Part	Description	Q'ty	Int	Page	Index	Note
14075299	RAM:FM1608-120-P	0→1	1	52	114	


23.ELECTRICAL SECTION 1



Model: Model K-C3		Date: 21-Jun-07	No.: MB245014
Modified Article: Parts catalog correction		Prepared by: Y.Yoshida	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Change/Reason: The part number for this part was missing from the Parts Catalog.

NEW Part	Description	Q'ty	Int	Page	Index	Note
14076612	EEPROM:AT24C64A-10PU-2.7	0→1	1	60	103	



Model: K-C2, C2.5 and C3		Date: 24-Jul-07	No.: MB245015
Modified Article: Parts number for Developer Type28		Prepared by: Y.Yoshida	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☐ Other	☐ To meet standards ()

Change: The service part in the table was separated into two parts.

Reason: The developer for the NA/EU markets will be supplied from REI.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B1219640	B1219640	Developer Type 28 Black(Asia)	1		35	13	Fig14
	B1219645	Developer Type 28 Black(NA,EU)					

Note) Kir-C2/C2.5 ; See MB No. MGenM008




Fig.14 (page 35)

Model:K-C3		Date: 25-Jul-07	No.: MB245016
Modified Article: Parts number for Rear cover		Prepared by: Y.Yoshida	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☐ Other	☐ To meet standards ()

Change/Reason: The part number in the table was corrected.

Incorrect part number	Correct part number	Description	Q'ty	Int	Page	Index	Note
B1211337	B2761337	Rear cover NA	1		9	6	Fig1




Fig.1 (page 8)

Model: K-C3		Date: 29-Aug-07	No.: MB245017
Modified Article: PCB BICU		Prepared by: Y. Yoshida	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety		

Old part number	New part number	Old Description	New Description	Q'ty	Int	Pg.	Index	Note
B2765106	B2765101	PCB:BICU:GDI:EXP:ASS'Y	PCB:BICU:EXP:ASS'Y	1 1		53 53	9 9	
B2765108	B2765103	PCB:BICU:GDI:AA:ASS'Y	PCB:BICU:AA:ASS'Y	1 1		53 53	9 9	

Change: The BICU assembly was changed to one that supports the BASIC, GDI expansion, and GW expansion models.

Reason: Only one is needed, since it supports the BASIC, GDI expansion and GW expansion models.

Note:

- P/N B2765101: For N.A., EU
P/N B2765103: For Asia
- The old BICU assemblies support the BASIC and GDI expansion models.
- The new BICU assemblies support the BASIC, GDI expansion and GW expansion models.

Model: K-C3 (For China only)		Date: 29-Aug-07	No.: MB245018
Modified Article: PCB BICU		Prepared by : Y.Yoshida	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety		

Incorrect part number	Correct part number	Description	Q'ty	Int	Page	Index	Note
-	B2775104	PCB:BICU:CHN:ASS'Y	1		83	*	

Change/Reason: The part number in the Parts Catalog was missing.

Model:K-C3		Date: 19-Sep-07	No.: MB245019
Modified Article: Parts number correction		Prepared by: Y.Yoshida	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☐ Other	☐ To meet standards ()

Change/Reason: The part number in the table was corrected.


Incorrect part number	Correct part number	Description	Q'ty	Int	Page	Index	Note
B0391251	B2761251	Shield Glass Cover	1		21	1	
B0391332	B2761332	Left Scanner Cover	1		9	2	
B0391333	B2761333	Rear Scanner Cover	1		9	4	
B0391335	B2761335	Right Scanner Cover	1		9	9	
B0391339	B2761339	Cover - Front Right Upper	1		9	11	
B0391347	B2761347	Right Rear Cover	1		9	10	
B0406136	B2766136	Left Lower Cover	1		11	19	
B0406139	B2766139	Rear Lower Cover	1		11	17	
B1211316	B2761316	Left Cove NA	1		11	2	
B1211337	B2761337	Rear Cover NA	1		9	6	MB16
B1211354	B2761354	Exit Cover NA	1		9	3	
B1211368	B2761368	Rear Cover: Exit NA	1		9	22	
B1221310	B2771310	Right Upper Front Cover NA	1		11	11	
B1221339	B2771339	Rear Cover NA	1		11	6	
B1221347	B2771347	Right Rear Cover NA	1		11	10	
B1221370	B2771370	Rear Exit Cover NA	1		11	26	
B1221372	B2771372	Sorter Cover NA	1		11	27	
B2431351	B2761351	Cover - Front NA	1		9	12	

Model: Model K-C3 GDI model		Date: 19-Sep-07	No.: MB245020
Modified Article: New part number was added		Prepared by: Y.Yoshida	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Change: This part was added.

Reason: Requests were received from the field.

NEW Part	Description	Q'ty	Int	Page	Index	Note
B8955171	PCB: DONGLE: ASS'Y	0→1	1	3	9	




Model: Model K-C3		Date: 4-Dec-07	No.: MB245021
Modified Article: Parts catalog correction		Prepared by: Y.Yoshida	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ Vendor change ☒ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Part Number	Old Description	New Description	Q'ty	Int	Page	Index	Note
B2431487	PCB Operation Panel	PCB OPERATION PANEL;K-C3bcd/Printer	1		13	19	
B2451487	PCB Operation Panel	PCB OPERATION PANEL;K-C3a/Basic	1		13	19	

Change: The descriptions for the parts in table were changed.

Reason: To clarify the difference between these two parts.




Model: Kir-C3		Date: 8-Feb-08	No.: MB245022
Modified Article: New part number was added		Prepared by: Y.Yoshida	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Change: This part was added.

Reason: Requests were received from the field.

NEW Part	Description	Q'ty	Int	Page	Index	Note
B2382753	DECAL:SIDE FENCE:MANUAL FEED	0→1	1	23	21	



Reissued: 28-Apr-08

Model:K-C3	Date: 3-Apr-08	No.: MB245023a
------------	----------------	----------------

MB Reissue

"Int" information has been added

Modified Article: Development roller Ass'y		Prepared by: Y.Yoshida	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☒ Other	☐ To meet standards ()

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B2593051	B2593052	Development roller Ass'y	1	O/O	35	6	

Change: The material of this part was changed.

Reason: To facilitate assembly.

Model: Kir-C3		Date: 7-May-08	No.: MB245024
Modified Article: Imaging unit		Prepared by: Y.Yoshida	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly ☒ Part standardization	☐ Vendor change ☐ To improve reliability ☐ Other	☐ To meet standards ()


Old P/N	New P/N	Description	Q'ty	Int	Page	Index	Note
B2431876	B2831876	Imaging Unit	1	O/O	21	*	

Change/Reason: Parts standardization with the Greatwall-C2.

Model: Kir-C3		Date: 20-May-08	No.: MB245025
Modified Article: Harness-Front Door Switch		Prepared by: Y.Yoshida	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☐ Other	☐ To meet standards ()

P/N	Description	Q'ty	Page	Index	Note
B1215205	Harness-Front Door Switch	1	53	26	

Change/Reason: This part was missing from the Parts Catalog.




Model: Kir-C3		Date: 31-Jul-08	No.: MB245026
Modified Article: DOOR:RIGHT		Prepared by: Y.Yoshida	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☒ Other	☐ To meet standards ()

P/N	Description	Q'ty	Page	Index	Note
B2592648	DOOR:RIGHT:C2B:ASS'Y	1	33	31	

Change: This part was newly added as a service part.

Reason: To meet requests from the field.

13.VERTICAL TRANSPORT (B269/B277)



Model: Kir-C3		Date: 2-Sep-08	No.: MB245027
Modified Article: TONER BOTTLE DC MOTOR		Prepared by: Y.Yoshida	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☒ Vendor change ☐ To improve reliability ☐ Other	☐ To meet standards ()

Old P/N	New P/N	Description	Q'ty	Int	Page	Index	Note
B2593310	B1213310	TONER BOTTLE DC MOTOR	1	O/O	51	6	

Change/Reason: Vendor change.


Model: Kir-C3		Date: 17-Sep-08	No.: MB245028
Modified Article: TONER BOTTLE DC MOTOR		Prepared by: Y.Yoshida	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☐ Other	☐ To meet standards ()

P/N	Old Description	New Description	Q'ty	Page	Index	Note
B0391234	Exit cover	Fusing cover for Kir-C3 a/b model	1	43	2	
B1231301	Fusing cover	Fusing cover for Kir-C3 cd model	1	43	2	

Change: The descriptions of these parts were changed.

Reason: To clarify the difference between the two parts.

18.PAPER EXIT SECTION



18.PAPER EXIT SECTION


Index No.	Part No.	Description	Qty Per Assembly
1	B121 1084	Heater Wire Cover	1
2	B039 1234	Exit Cover	1
2	B123 1301	Fusing Cover	1
3	B259 4471	Exit Roller 2	1
4	B039 4473	Ring:Exit Roller	6
5	AA08 2063	Bushing - 8x10x5	2
6	B039 1082	Door Switch Bracket	1
7	B121 5205	Harness - Front Door Switch	1
8	B039 1096	Door Switch Lever - 7	1

Model: Kir-C3		Date: 8-Oct-08	No.: MB245029
Modified Article: TONER BOTTLE DC MOTOR		Prepared by: Y.Yoshida	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☒ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☐ Other	☐ To meet standards ()

Old P/N	New P/N	New Description	Q'ty	Int	Page	Index	Note
B2431916	B2761917	Laser Diode Unit	1	O/O	21	15	

Change: The material of this part was changed.

Reason: To facilitate assembly.



Reissued: 30-Jan-08

Model:K-C3	Date: 28-Jan-08	No.: MB245030
------------	-----------------	---------------

MB Reissue
The MB Number was corrected (the incorrect MB No. was for the Panda).
Note: The original MB (MB245A04) was cancelled.

Modified Article: Development roller Ass'y		Prepared by: Y.Yoshida	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☒ Vendor change ☐ To improve reliability ☐ Other	☐ To meet standards ()

Old P/N	New P/N	Description	Q'ty	Int	Page	Index	Note
B1213310	B2763310	TONER BOTTLE DC MOTOR	1	O/O	51	6	

Change/Reason: Vendor change.

Note: The following is the P/N change history for this part.

B1213310 → B2593310 (vendor change)

→ B1213310 (vendor change) → B2763310 (vendor change)



Part Change Information List

Date: March 18, 2009

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number
Kir-C3	B245	200903		B1214103	B2924103	FRAME:FUSING	1	1	O/O		41	37					V0804361
Kir-C3	B245	200903		B1213310	B2763310	DC MOTOR:TONER BOTTLE:KIR-C3:ASS'Y	1	1	O/O		51	6					V0804688





Part Change Information List

Date: April 30, 2009

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number
Kir-C3	B245	200904		08010149	AA143592	SCREW- M4X6	1	1	X/O		53	104					V0900053



Part Change Information List

Date: June 30, 2009

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
GW-C1	B283	200906		B2431435		LED-A:100*645078:D/E			0	X/O	3	20			X		V0901376	
GW-C1	B283	200906		19070012	19070096	SDRAM:128M:2MX16X4:133MHZ:G8	1	1	O/O		67	261					V0901263	9020441



Part Change Information List

Date: July 31, 2009

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.
K-C3	B245	200907		B1214085	B2454054	FRAME:PRESSURE:PRINTING	1	1	O/O		41	28					V0901625





Part Change Information List

Date: October 30, 2009

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
K-C3	B245	200910		A1931793	A1931705	SHEET:PHOTOINTERRUPTOR	1	1	X/O		15	5					V0901804	9060321
K-C3	B245	200910		B0391701	B0391705	BRACKET:IDLER	2	2	X/O		19	4					V0902604	9091280
K-C3	B268	200910		B0391701	B0391705	BRACKET:IDLER	2	2	X/O		19	4					V0902605	
K-C3	B269	200910		B0391701	B0391705	BRACKET:IDLER	2	2	X/O		19	4					V0902605	



Part Change Information List

Date: October 30, 2009

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
K-C3b	B276	200910		A1931793	A1931705	SHEET:PHOTOINTERRUPTOR	1	1	X/O		15	5					V0901804	9060321
K-C3b	B276	200910		B0391701	B0391705	BRACKET:IDLER	2	2	X/O		19	4					V0902604	9091280



Part Change Information List

Date: October 30, 2009

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
K-C3cd	B277	200910		A1931793	A1931705	SHEET:PHOTOINTERRUPTOR	1	1	X/O		15	5					V0901804	9060321
K-C3cd	B277	200910		B0391701	B0391705	BRACKET:IDLER	2	2	X/O		19	4					V0902604	9091280



Part Change Information List

Date: November 30, 2009

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
K-C3	B245	200911		B4061232	B2451232	PRESSURE PLATE:ASS'Y	1	1	O/O		3	*					V0902693	9091902
K-C3	B245	200911		B0391701	B0391705	BRACKET:IDLER	2	2	X/O		19	4					V0902605	
K-C3	B245	200911		B1214085	B2454054	FRAME:PRESSURE:PRINTING	1	1	O/O		41	28					V0901642	
K-C3	B268	200911		B1214085	B2454054	FRAME:PRESSURE:PRINTING	1	1	O/O		41	28					V0901642	
K-C3	B269	200911		B1214085	B2454054	FRAME:PRESSURE:PRINTING	1	1	O/O		41	28					V0901642	



Part Change Information List

Date: November 30, 2009

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
K-C3b	B276	200911		B0391701	B0391705	BRACKET:IDLER	2	2	X/O		19	4					V0902605	
K-C3b	B276	200911		B1214085	B2454054	FRAME:PRESSURE:PRINTING	1	1	O/O		41	28					V0901642	



Part Change Information List

Date: November 30, 2009

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
K-C3cd	B277	200911		B0391701	B0391705	BRACKET:IDLER	2	2	X/O		19	4					V0902605	
K-C3cd	B277	200911		B1214085	B2454054	FRAME:PRESSURE:PRINTING	1	1	O/O		41	28					V0901642	



Part Change Information List

Date: December 29, 2009

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
GW-C1	B283	200912			B2381845	SEAL:EXPOSURE GLASS	0	1			11	19			Y		V0902945	9110595
GW-C1	B283	200912			B2381845	SEAL:EXPOSURE GLASS	1	2			11	19			Y		V0903068	9111148
GW-C1	B283	200912		B2593310	B2763310	DC MOTOR:TONER BOTTLE:KIR-C3:ASS'Y	1	1	O/O		45	6					V0903059	



Part Change Information List

Date: December 29, 2009

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
K-C3	B245	200912			B2381845	SEAL:EXPOSURE GLASS	0	1			15	19			Y		V0902945	9110595
K-C3	B245	200912			B2381845	SEAL:EXPOSURE GLASS	1	2			15	19			Y		V0903068	9111148
K-C3	B245	200912		B2593310	B2763310	DC MOTOR:TONER BOTTLE:KIR-C3:ASS'Y	1	1	O/O		51	6					V0903059	
K-C3	B268	200912		B2593310	B2763310	DC MOTOR:TONER BOTTLE:KIR-C3:ASS'Y	1	1	O/O		51	6					V0903059	
K-C3	B269	200912		B2593310	B2763310	DC MOTOR:TONER BOTTLE:KIR-C3:ASS'Y	1	1	O/O		51	6					V0903059	



Part Change Information List

Date: December 29, 2009

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
K-C3b	B276	200912			B2381845	SEAL:EXPOSURE GLASS	0	1			15	19			Y		V0902945	9110595
K-C3b	B276	200912			B2381845	SEAL:EXPOSURE GLASS	1	2			15	19			Y		V0903068	9111148
K-C3b	B276	200912		B2593310	B2763310	DC MOTOR:TONER BOTTLE:KIR-C3:ASS'Y	1	1	O/O		51	6					V0903059	



Part Change Information List

Date: December 29, 2009

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
K-C3cd	B277	200912			B2381845	SEAL:EXPOSURE GLASS	0	1			15	19			Y		V0902945	9110595
K-C3cd	B277	200912			B2381845	SEAL:EXPOSURE GLASS	1	2			15	19			Y		V0903068	9111148
K-C3cd	B277	200912		B2593310	B2763310	DC MOTOR:TONER BOTTLE:KIR-C3:ASS'Y	1	1	O/O		51	6					V0903059	



Part Change Information List

Date: February 26, 2010



Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
K-C3	B245	201002		B4061384		FEELER - PLATEN COVER	1	0	X/O		9	8	A		Y		V1000025	9110611
K-C3	B245	201002		B4841383	B2451383	BRACKET:PRESSURE PLATE:FIX:PANDA	1	1	O/O		9	10					V0902693	9091902
K-C3	B245	201002		B4061232	B2451231	PRESSURE PLATE:ASS'Y	1	1	O/O		9	11					V0902693	9091902
K-C3	B245	201002		B2451232	B2451231	PRESSURE PLATE:ASS'Y	1	1	X/O		9	11	A		Y		V1000025	9110611
K-C3	B245	201002		04504012N		TAPPING SCREW:4X12	15	14			9	101	A		Y		V1000025	9110611
K-C3	B245	201002		B0395744	B0395746	POWER SUPPLY CORD:STOPPER:CHN:ASS'Y	1	1	O/O		43	2					V0902723	9100512



Part Change Information List

Date: March 31, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
K-C3	B245	201003			B2381845	SEAL:EXPOSURE GLASS	0	2			14	#19			RB245029		V1000260	10020249



Part Change Information List

Date: April 30, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
K-C3	B245	201002	Cancel	B4061232	B2451231	PRESSURE PLATE:ASS'Y	1	1	O/O		9	11					V0902693	9091902
K-C3	B245	201002	Cancel	04504012N		TAPPING SCREW:4X12	15	14			9	101	A		No	This information was incorrect.	V1000025	9110611
K-C3	B245	201002	Cancel	B2451232	B2451231	PRESSURE PLATE:ASS'Y	1	1	X/O		9	11	A		No	This information was incorrect.	V1000025	9110611
K-C3	B245	201002	Cancel	B4061384		FEELER - PLATEN COVER	1	0	X/O		9	8	A		No	This information was incorrect.	V1000025	9110611



Part Change Information List

Date: May 31, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
K-C3	B245	201005		B0391670	B0391699	STEPPER MOTOR:MM42:2.9W	1	1	O/O		19	15					V1000084	9120867
K-C3	B276	201005		B0391670	B0391699	STEPPER MOTOR:MM42:2.9W	1	1	O/O		19	15					V1000084	9120867
K-C3	B277	201005		B0391670	B0391699	STEPPER MOTOR:MM42:2.9W	1	1	O/O		19	15					V1000084	9120867
K-C3	B245	201005		AW500034	B0392645	ROTARY SWITCH	1	1	O/O		23	9					V0901331	9041377
K-C3	B268	201005		AW500034	B0392645	ROTARY SWITCH	1	1	O/O		23	9					V0901331	9041377
K-C3	B269	201005		AW500034	B0392645	ROTARY SWITCH	1	1	O/O		23	9					V0901331	9041377
K-C3	B276	201005		AW500034	B0392645	ROTARY SWITCH	1	1	O/O		23	9					V0901331	9041377
K-C3	B277	201005		AW500034	B0392645	ROTARY SWITCH	1	1	O/O		23	9					V0901331	9041377
K-C3	B245	201005	Cancel	B1214103	B2824103	FRAME:FUSING	1	1	O/O		41	37					V0804361	



Part Change Information List

Date: May 31, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
K-C3	B245	201002	Cancel	B4061232	B2451231	PRESSURE PLATE:ASS'Y	1	1	O/O		9	11					V0902693	9091902
K-C3	B245	201002	Cancel	04504012N		TAPPING SCREW:4X12	15	14			9	101	A			This information was incorrect.	V1000025	9110611
K-C3	B245	201002	Cancel	B2451232	B2451231	PRESSURE PLATE:ASS'Y	1	1	X/O		9	11	A			This information was incorrect.	V1000025	9110611
K-C3	B245	201002	Cancel	B4061384		FEELER - PLATEN COVER	1	0	X/O		9	8	A			This information was incorrect.	V1000025	9110611
K-C3	B245	201005	Cancel	B1214103	B2824103	FRAME:FUSING	1	1	O/O		41	37					V0804361	



Part Change Information List

Date: June 30, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
K-C3	B245	200903	cancel	B1214103	B2824103	FRAME:FUSING	1	1	O/O		41	37					V0804361	8091037



Part Change Information List

Date: Jun 30, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
K-C3	B245	201006			B2431451	CASE:OPERATION SUB-UNIT	0	1			13	#20			RB245034		V1001059	
K-C3	B268	201006			B2431451	CASE:OPERATION SUB-UNIT	0	1			13	#20			RB245034		V1001059	
K-C3	B269	201006			B2431451	CASE:OPERATION SUB-UNIT	0	1			13	#20			RB245034		V1001059	
K-C3	B276	201006			B2431451	CASE:OPERATION SUB-UNIT	0	1			13	#20			RB245034		V1001059	
K-C3	B277	201006			B2431451	CASE:OPERATION SUB-UNIT	0	1			13	#20			RB245034		V1001059	
K-C3	B277	201006		B2591812	B2591813	HOLDER:LENS:ASSY	1	1	O/O		15	9					V1000348	10020964
K-C3	B245	201006		AA082063	B1202063	BUSHING - 4MM	2	2	O/O		43	5					V1001044	10050505
K-C3	B276	201006		AA082063	B1202063	BUSHING - 4MM	2	2	O/O		43	5					V1001044	10050505
K-C3	B277	201006		AA082063	B1202063	BUSHING - 4MM	2	2	O/O		43	5					V1001044	10050505



Part Change Information List

Date: Aug 31, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
Kir-G3	B245	201005	Cancel	B1214103	B2824103	FRAME:FUSING	4	4	O/O		41	37				This information was incorrect.	V0804361	



Part Change Information List

Date: September 30, 2010

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
K-C3	B245	201009		B1211128	B2821128	GROUND	1	1	O/O		51	9					V0901332	9041380
K-C3	B268	201009		B1211128	B2821128	GROUND	1	1	O/O		51	9					V0901332	9041380
K-C3	B269	201009		B1211128	B2821128	GROUND	1	1	O/O		51	9					V0901332	9041380
K-C3	B276	201009		B1211128	B2821128	GROUND	1	1	O/O		51	9					V0901332	9041380
K-C3	B277	201009		B1211128	B2821128	GROUND	1	1	O/O		51	9					V0901332	9041380



Part Change Information List

Date: November 30, 2011

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
K-C3cd	B277	201106			B2441473	SHEET:OPERATION PANEL:CHN	0	1			13	16			RB245039		V1101134	



Part Change Information List

Date: September 30, 2011

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
K-C3	B245	201109		B0391961	B2831961	SHIELD GLASS:ASS'Y	1	1	O/O		21	6					V1100088	
K-C3	B245	201109		AX310046	AX310050	TOTAL COUNTER:7FIG:24V	1	1	O/O		39	16					V1102240	11081489
K-C3	B268	201109		B0391961	B2831961	SHIELD GLASS:ASS'Y	1	1	O/O		21	6					V1100088	
K-C3	B269	201109		B0391961	B2831961	SHIELD GLASS:ASS'Y	1	1	O/O		21	6					V1100088	
K-C3	B276	201109		B0391961	B2831961	SHIELD GLASS:ASS'Y	1	1	O/O		21	6					V1100088	
K-C3	B276	201109		AX310046	AX310050	TOTAL COUNTER:7FIG:24V	1	1	O/O		39	16					V1102240	11081489
K-C3	B277	201109		B0391961	B2831961	SHIELD GLASS:ASS'Y	1	1	O/O		21	6					V1100088	
K-C3	B277	201109		AX310046	AX310050	TOTAL COUNTER:7FIG:24V	1	1	O/O		39	16					V1102240	11081489



Part Change Information List

Date: November 30, 2011

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
K-C3	B245	201111		B2591812	B2591813	HOLDER:LENS:ASSY	1	1	O/O		15	9					V1101097	11050620
K-C3	B268	201111		B2591812	B2591813	HOLDER:LENS:ASSY	1	1	O/O		15	9					V1101097	11050620
K-C3	B269	201111		B2591812	B2591813	HOLDER:LENS:ASSY	1	1	O/O		15	9					V1101097	11050620
K-C3	B276	201111		B2591812	B2591813	HOLDER:LENS:ASSY	1	1	O/O		15	9					V1101097	11050620



Part Change Information List

Date: April 27, 2012

Model	Code	PCIL No.	PCIL Correction	Old part number	New part number	Description	Old Qty	New Qty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. No.	ECN No.
K-C3	B248	201204		B1211126	D1581150	GUIDE HARNESS	1	1	O/O		43	43					V1200706	12031888
K-C3	B276	201204		B1211126	D1581150	GUIDE HARNESS	1	1	O/O		43	43					V1200706	12031888
K-C3	B277	201204		B1211126	D1581150	GUIDE HARNESS	1	1	O/O		43	43					V1200706	12031888

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
K-C3	B245	201210		B0391144	AA082178	PLAIN SHAFT BEARING:DIA8:DIA16X9	1	1	O/O		51	7					V1201832	12070643
K-C3	B276	201210		B0391144	AA082178	PLAIN SHAFT BEARING:DIA8:DIA16X9	1	1	O/O		51	7					V1201832	12070643
K-C3	B277	201210		B0391144	AA082178	PLAIN SHAFT BEARING:DIA8:DIA16X9	1	1	O/O		51	7					V1201832	12070643

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
K-C3	B245	201211		AA082110	AA082177	BUSHING:DIA8:22	1	1	O/O		27	23					V1201832	12070643
K-C3	B276	201211		AA082110	AA082177	BUSHING:DIA8:22	1	1	O/O		27	23					V1201832	12070643
K-C3	B277	201211		AA082110	AA082177	BUSHING:DIA8:22	1	1	O/O		27	23					V1201832	12070643
K-C3	B245	201211		53041639	AA082176	PLAIN SHAFT BEARING:DIA8:DIA16X6	1	1	O/O		51	24					V1201832	12070643
K-C3	B276	201211		53041639	AA082176	PLAIN SHAFT BEARING:DIA8:DIA16X6	1	1	O/O		51	24					V1201832	12070643
K-C3	B277	201211		53041639	AA082176	PLAIN SHAFT BEARING:DIA8:DIA16X6	1	1	O/O		51	24					V1201832	12070643



Part Change Information List

Date: March 29, 2013

Model	Code	PCIL		Old part number	New part number	Description	Old		New	3DPC	Page	Index	Set		RTB	Note	Ref Number	ECN
		Number	Correction				Qty	Qty	Int				Int	Int				
K-C3	B245	201303		B0391098	D1581315	COIL SPRING-SAFETY SWITCH-C4	1	1	X/O		43	12					V1300474	13020068
K-C3	B276	201303		B0391098	D1581315	COIL SPRING-SAFETY SWITCH-C4	1	1	X/O		43	12					V1300474	13020068
K-C3	B277	201303		B0391098	D1581315	COIL SPRING-SAFETY SWITCH-C4	1	1	X/O		43	12					V1300474	13020068
K-C3	B245	201303		B0391099	D1581314	LEVER-SAFETY SWITCH-FRONT	1	1	X/O		43	15					V1300474	13020068
K-C3	B276	201303		B0391099	D1581314	LEVER-SAFETY SWITCH-FRONT	1	1	X/O		43	15					V1300474	13020068
K-C3	B277	201303		B0391099	D1581314	LEVER-SAFETY SWITCH-FRONT	1	1	X/O		43	15					V1300474	13020068
K-C3	B245	201303		B0391164	AA043701	SYNCHRONOUS BELT-S2M	1	1	O/O		51	3					V1300500	13020197
K-C3	B276	201303		B0391162	AA043701	SYNCHRONOUS BELT-S2M	1	1	O/O		51	3					V1300500	13020197
K-C3	B277	201303		B0391162	AA043701	SYNCHRONOUS BELT-S2M	1	1	O/O		51	3					V1300500	13020197
K-C3	B245	201303		B0391145	AB010500	GEAR-SLOW DOWN-DRUM-NO.1	1	1	O/O		51	14					V1300500	13020197
K-C3	B276	201303		B0391145	AB010500	GEAR-SLOW DOWN-DRUM-NO.1	1	1	O/O		51	14					V1300500	13020197
K-C3	B277	201303		B0391145	AB010500	GEAR-SLOW DOWN-DRUM-NO.1	1	1	O/O		51	14					V1300500	13020197
K-C3	B245	201303		B0391146	AB010501	GEAR-SLOW DOWN-DRUM-NO.2	1	1	O/O		51	15					V1300500	13020197
K-C3	B276	201303		B0391146	AB010501	GEAR-SLOW DOWN-DRUM-NO.2	1	1	O/O		51	15					V1300500	13020197
K-C3	B277	201303		B0391146	AB010501	GEAR-SLOW DOWN-DRUM-NO.2	1	1	O/O		51	15					V1300500	13020197



Part Change Information List

Date: April 26, 2013

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set Int	RTB	Note	Ref Number	ECN Number
K-C3	B268	201304		AA082110	AA082177	BUSHING:DIA8:22	1	1	O/O		27	23				V1201839	
K-C3	B269	201304		AA082110	AA082177	BUSHING:DIA8:22	1	1	O/O		27	23				V1201839	
K-C3	B245	201304		B0393395	D1583395	GROUND PLATE:TONER SUPPLY UNIT	1	1	O/O		39	17				V1300473	13020067
K-C3	B276	201304		B0393395	D1583395	GROUND PLATE:TONER SUPPLY UNIT	1	1	O/O		39	17				V1300473	13020067
K-C3	B277	201304		B0393395	D1583395	GROUND PLATE:TONER SUPPLY UNIT	1	1	O/O		39	17				V1300473	13020067



Part Change Information List

Date: May 31, 2013

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
K-C3	B245	201305		AA100015	52152621	SNAP RING - M6	4	4	O/O		27	8					V1301719	13040527
K-C3	B276	201305		AA100015	52152621	SNAP RING - M6	4	4	O/O		27	8					V1301719	13040527
K-C3	B277	201305		AA100015	52152621	SNAP RING - M6	5	5	O/O		27	8					V1301719	13040527



Part Change Information List

Date: June 28, 2013

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Qty	New Qty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
K-C3	B245	201306		B0391162	AA043701	SYNCHRONOUS BELT:S2M	1	1	O/O		51	3					V1300567	
K-C3	B268	201306		B0391162	AA043701	SYNCHRONOUS BELT:S2M	1	1	O/O		51	3					V1300567	
K-C3	B269	201306		B0391162	AA043701	SYNCHRONOUS BELT:S2M	1	1	O/O		51	3					V1300567	
K-C3	B276	201306		B0391162	AA043701	SYNCHRONOUS BELT:S2M	1	1	O/O		51	3					V1300567	
K-C3	B277	201306		B0391162	AA043701	SYNCHRONOUS BELT:S2M	1	1	O/O		51	3					V1300567	



Part Change Information List

Date: October 31, 2013

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set Int	RTB	Note	Ref Number	ECN Number
K-C3	B245	201310		B0391146	AB010501	GEAR:SLOW DOWN:DRUM:NO.2	1	1	O/O		51	15				V1300567	
K-C3	B268	201310		B0391146	AB010501	GEAR:SLOW DOWN:DRUM:NO.2	1	1	O/O		51	15				V1300567	
K-C3	B269	201310		B0391146	AB010501	GEAR:SLOW DOWN:DRUM:NO.2	1	1	O/O		51	15				V1300567	
K-C3	B276	201310		B0391146	AB010501	GEAR:SLOW DOWN:DRUM:NO.2	1	1	O/O		51	15				V1300567	
K-C3	B277	201310		B0391146	AB010501	GEAR:SLOW DOWN:DRUM:NO.2	1	1	O/O		51	15				V1300567	



Part Change Information List

Date: November 29, 2013

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set Int	RTB	Note	Ref Number	ECN Number
K-C3	B245	201311		B0391145	AB010500	GEAR:SLOW DOWN:DRUM:NO.1	1	1	O/O		51	14				V1300567	
K-C3	B268	201311		B0391145	AB010500	GEAR:SLOW DOWN:DRUM:NO.1	1	1	O/O		51	14				V1300567	
K-C3	B269	201311		B0391145	AB010500	GEAR:SLOW DOWN:DRUM:NO.1	1	1	O/O		51	14				V1300567	
K-C3	B276	201311		B0391145	AB010500	GEAR:SLOW DOWN:DRUM:NO.1	1	1	O/O		51	14				V1300567	
K-C3	B277	201311		B0391145	AB010500	GEAR:SLOW DOWN:DRUM:NO.1	1	1	O/O		51	14				V1300567	



Part Change Information List

Date: January 31, 2014

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
K-C3	B245	201401		AA082101	AA082184	PLAIN SHAFT BEARING:DIA6XDIA10X6	1	1	O/O		29	15					V1303940	13060943
K-C3b	B276	201401		AA082101	AA082184	PLAIN SHAFT BEARING:DIA6XDIA10X6	1	1	O/O		29	15					V1303940	13060943
K-C3cd	B277	201401		AA082101	AA082184	PLAIN SHAFT BEARING:DIA6XDIA10X6	1	1	O/O		29	15					V1303940	13060943



Part Change Information List

Date: June 30, 2014

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
K-C3	B245	201406		11033733	11034777	CONNECTOR:00 6216 005 808+	1	1	O/O		71	123					V1401434	08090798
K-C3	B245	201406		14001163	14001253	TRANSISTOR:2SA1979UF	1	1	O/O		71	130					V1401434	08090798
K-C3	B245	201406		14011228	14011414	FET:SI3433BDV-E3	1	1	O/O		71	132					V1401434	08090798
K-C3	B245	201406		14021911	14021995	DIODE:SDS511	13	13	O/O		72	136					V1401434	08090798
K-C3	B245	201406		14021912	14021932	DIODE:SDS142WMF	3	3	O/O		72	137					V1401434	08090798
K-C3	B245	201406		14031266	14030996	LED - SML-310VT	1	1	O/O		72	138					V1401434	08090798
K-C3	B245	201406		14081290	14082537	SERIES REGULATOR:KIA7805API/P	1	1	O/O		72	152					V1401434	08090798
K-C3	B245	201406		14081428	14082540	SERIES REGULATOR:KIA7812API/P	1	1	O/O		72	153					V1401434	08090798
K-C3	B245	201406		19070012	19070096	SDRAM:128M:2MX16X4:133MHZ:G8	1	1	O/O		73	249					V1401434	08090798
K-C3b	B276	201406		11033733	11034777	CONNECTOR:00 6216 005 808+	1	1	O/O		83	132					V1401434	08090798
K-C3cd	B277	201406		11033733	11034777	CONNECTOR:00 6216 005 808+	1	1	O/O		83	132					V1401434	08090798
K-C3b	B276	201406		14001163	14001253	TRANSISTOR:2SA1979UF	1	1	O/O		84	139					V1401434	08090798
K-C3cd	B277	201406		14001163	14001253	TRANSISTOR:2SA1979UF	1	1	O/O		84	139					V1401434	08090798
K-C3b	B276	201406		14011228	14011414	FET:SI3433BDV-E3	1	1	O/O		84	141					V1401434	08090798
K-C3cd	B277	201406		14011228	14011414	FET:SI3433BDV-E3	1	1	O/O		84	141					V1401434	08090798
K-C3b	B276	201406		14021911	14021995	DIODE:SDS511	14	14	O/O		84	145					V1401434	08090798
K-C3cd	B277	201406		14021911	14021995	DIODE:SDS511	14	14	O/O		84	145					V1401434	08090798
K-C3b	B276	201406		14021912	14021932	DIODE:SDS142WMF	3	3	O/O		84	146					V1401434	08090798
K-C3cd	B277	201406		14021912	14021932	DIODE:SDS142WMF	3	3	O/O		84	146					V1401434	08090798
K-C3b	B276	201406		14031266	14030996	LED - SML-310VT	1	1	O/O		84	147					V1401434	08090798
K-C3cd	B277	201406		14031266	14030996	LED - SML-310VT	1	1	O/O		84	147					V1401434	08090798
K-C3b	B276	201406		14081290	14082537	SERIES REGULATOR:KIA7805API/P	1	1	O/O		84	162					V1401434	08090798
K-C3cd	B277	201406		14081290	14082537	SERIES REGULATOR:KIA7805API/P	1	1	O/O		84	162					V1401434	08090798
K-C3b	B276	201406		14081428	14082540	SERIES REGULATOR:KIA7812API/P	1	1	O/O		84	163					V1401434	08090798
K-C3cd	B277	201406		14081428	14082540	SERIES REGULATOR:KIA7812API/P	1	1	O/O		84	163					V1401434	08090798
K-C3b	B276	201406		19070012	19070096	SDRAM:128M:2MX16X4:133MHZ:G8	1	1	O/O		85	261					V1401434	08090798
K-C3cd	B277	201406		19070012	19070096	SDRAM:128M:2MX16X4:133MHZ:G8	1	1	O/O		85	261					V1401434	08090798



Part Change Information List

Date: August 29, 2014

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
K-C3	B245	201408		11033733	11034777	CONNECTOR:00 6216 005 808+	1	1	O/O		71	125					V1401435	
K-C3	B268	201408		11033733	11034777	CONNECTOR:00 6216 005 808+	1	1	O/O		83	132					V1401435	
K-C3	B269	201408		11033733	11034777	CONNECTOR:00 6216 005 808+	1	1	O/O		83	132					V1401435	
K-C3b	B276	201408		11033733	11034777	CONNECTOR:00 6216 005 808+	1	1	O/O		83	132					V1401435	
K-C3cd	B277	201408		11033733	11034777	CONNECTOR:00 6216 005 808+	1	1	O/O		83	132					V1401435	



Part Change Information List

Date: October 31, 2014

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
K-C3	B245	201410		B0391971	B0391972	COVER:OPTICAL HOUSING	1	1	O/O		21	12			Y		V1402313	
K-C3	B268	201410		B0391971	B0391972	COVER:OPTICAL HOUSING	1	1	O/O		21	12			Y		V1402313	
K-C3	B269	201410		B0391971	B0391972	COVER:OPTICAL HOUSING	1	1	O/O		21	12			Y		V1402313	
K-C3b	B276	201410		B0391971	B0391972	COVER:OPTICAL HOUSING	1	1	O/O		21	12			Y		V1402313	
K-C3cd	B277	201410		B0391971	B0391972	COVER:OPTICAL HOUSING	1	1	O/O		21	12			Y		V1402313	



Part Change Information List

Date: June 4, 2015

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
K-C3	B245	201505		B2681085	12042612	MICRO SWITCH:D3V-16506-3C25	2	2	O/O	N	43	101					V1403150	
K-C3	B268	201505		B2681085	12042612	MICRO SWITCH:D3V-16506-3C25	2	2	O/O	N	43	101					V1403150	
K-C3	B269	201505		B2681085	12042612	MICRO SWITCH:D3V-16506-3C25	2	2	O/O	N	43	101					V1403150	



Part Change Information List

Date: October 2, 2015

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
K-C3	B245	201509		B2831971	B0391972	COVER:ASS'Y	0	---	O/O	N	21	12					V1402313	



Part Change Information List

Date: October 4, 2016

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
K-C3	B245	201609		14075454		IC - SN74LV86APW		---	X/O	N	72	145					V1603062	
K-C3	B268	201609		14075454		IC - SN74LV86APW		---	X/O	N	72	145					V1603062	
K-C3	B269	201609		14075454		IC - SN74LV86APW		---	X/O	N	72	145					V1603062	