

Errata

This supplement provides a correction for Driver Installation Guide provided with this machine.

The location of HDI driver, described in step 10 on pages 25 and 26, has been changed.

After selecting the DRIVERS and HDI folders, you need to double-click the folder with your manufacturer's name to select the folder with your AutoCAD version.

© 2012

Printed in China

EN (GB) EN (US) EN (AU)

D124-7539



D1247539