


Notes for Users

Additional Information

Page 22 "Positions of WARNING and CAUTION labels", Read This First



CWU6012

- 1
Do not touch the parts a label indicates. The inside and surface of the fusing unit could be very hot. Caution should be taken when removing misfed paper.
- 2
This label indicates the weight of the unit. However, this label is meant for customer engineers and operators who have received training. Do not lift a unit that has this label.
- 3, 4, 5, and 6
Do not touch the parts a label indicates. Otherwise, an injury might occur.
- 7
Keep your fingers and other body parts away from moving parts. Do not pull out other units when replacing the developer.
- 8
This unit uses a laser radiation. Do not attempt to disassemble or modify this machine.
- 9
For correct handling of the waste toner bottle, see "Handling the machine's supplies".
- 10
Keep your hands clear of the parts a label indicates. Otherwise, you might trap your fingers and an injury might occur.

