

Reissued: 14-Sep-15

Model: Endpoint	Date: 18-Oct-11	No.: RD569001e
-----------------	-----------------	----------------

**For Users in North America Only**  
**Users in other regions should ignore this RTB.**  
**RTB Reissue**

The items in ***bold italics*** have been corrected or added.

Subject: Firmware Release Note: Embedded Endpoint		Prepared by: H. Masuhara	
From: Solution Support Sec., Solution Support Dept.			
Classification:	<input type="checkbox"/> Troubleshooting	<input type="checkbox"/> Part information	<input type="checkbox"/> Action required
	<input type="checkbox"/> Mechanical	<input type="checkbox"/> Electrical	<input type="checkbox"/> Service manual revision
	<input type="checkbox"/> Paper path	<input type="checkbox"/> Transmit/receive	<input type="checkbox"/> Retrofit information
	<input type="checkbox"/> Product Safety	<input checked="" type="checkbox"/> Other (Firmware)	<input checked="" type="checkbox"/> Tier 2

This RTB has been issued to announce the firmware release information for the **Embedded Endpoint**.

Version	Program No.	Effective Date	Availability of RFU
<b><i>1.0.6</i></b>	<b><i>D5690011106</i></b>	<b><i>September 2015 production</i></b>	<b><i>Not available</i></b>
1.0.5	D5690011105	November 2014 production	Not available
1.0.4	D5690011104	September 2013 production	Not available
1.0.3	D5690011103	November 2011 production	Not available
1.0.2	D5690011102	October 2011 production	Not available
1.0.1	D5690011101	March 2011 production	Not available
1.0	D5690011	1st Mass production	Not available

**Note: Definition of Availability of RFU via @Remote**  
**“Available”:** The firmware can be updated via RFU or SD card.  
**“Not available”:** The firmware can only be updated via SD card.

Version	Modified Points or Symptom Corrected
<b><i>1.0.6</i></b>	<p>1) <b><i>Device Support Changes</i></b>  <b><i>Intelligent Device Manager -MFP Client V1.0.6 now supports the following devices:</i></b>  <b><i>Aficio SP C821DN / Aficio SP C831DN / MP 3053SP / MP 3353SP / MP C5503SPMP C6502SP / SP 4510SF / SP 4520DN / SP 6430DN / MP 3054SP / MP 4054SP / MP 6054SP</i></b></p> <p>2) <b><i>Fixed:</i></b>  <b><i>Failure of monitoring service when NullPointerException occurs.</i></b></p>
1.0.5	<p>1) Device Support Changes  Intelligent Device Manager - MFP Client V1.0.5 now supports the following devices (the V1.0.4 limitation has been resolved):  Aficio MP C3000 / Aficio MP C4500 / Aficio MP 5500 / Aficio MP 6000  Aficio MP 7000 / Aficio 3224C / Aficio 3245C / Aficio 3035 / Aficio 3045</p> <p>2) Specification Changes  - Supports overwrite installations.</p> <p>3) Fixed:  - The failure of a print log event when a SocketException occurs (it now re-sends the event).</p>

**Reissued: 14-Sep-15**

Model: <b>Endpoint</b>	Date: 18-Oct-11	No.: RD569001e
------------------------	-----------------	----------------

<b>Version</b>	<b>Modified Points or Symptom Corrected</b>
1.0.4	<p>1) Device Support Changes                      Intelligent Device Manager -MFP Client V1.0.4 now supports the following devices:                      Aficio MP 301SPF / Aficio MP2852 / Aficio MP3352SP / Aficio MP C3502 / Aficio MP C5502 / Aficio MP 4002 / Aficio MP 6002 / Aficio MP 7502 / MP C3503SP / Aficio SP C430DN / Aficio SP 8300DN</p> <p>Intelligent Device Manager -MFP Client V1.0.4 does NOT support the following devices:                      Aficio MP C3000 / Aficio MP C4500 / Aficio MP 5500 / Aficio MP 6000 / Aficio MP 7000 / Aficio 3224C / Aficio 3245C / Aficio 3035 / Aficio 3045</p> <p>For these devices, please install the previous version of Intelligent Device Manager - MFP Client (V1.0.3).</p>
1.0.3	<p>1) Fixed:                      Install fails on some devices.</p>
1.0.2	<p>1) Device Support Changes                      Intelligent Device Manager -MFP Client V1.0.2 now supports the following devices:                      Aficio SP 4310N/Aficio MP 201SPF/Aficio SP 5200DN/Aficio SP 5210DN/Aficio SP 5210SR/Aficio SP C320DN.</p> <p>2) Specification Changes                      Improved internal performance by reducing the number of SD card writes operations.</p>
1.0.1	<p>1) Device Support Changes                      Intelligent Device Manager -MFP Client V1.0.1 now supports the following devices:                      Aficio 3224C/Aficio 3245C/Aficio 3035/Aficio 3045/Aficio MP C2500/Pro C900S/Aficio MP 4001/Aficio MP 2851/Aficio MP 3351/Aficio MP C6501/Aficio MP C3001/Aficio MP C3501/Aficio MP C4501/Aficio MP C5501/Aficio SP 6330N.</p> <p>2) Fixed                      The incorrect power consumption value of low power mode was used for the following 2 devices:                      Aficio MP5500/Aficio MPC2550</p>
1.0	1st Mass production

Reissued: 14-Sep-15

Model: Endpoint	Date: 18-Oct-11	No.: RD569002c
-----------------	-----------------	----------------

**For Users in North America Only**  
**Users in other regions should ignore this RTB.**  
**RTB Reissue**

The items in ***bold italics*** have been corrected or added.

Subject: Firmware Release Note: Endpoint Service Tools		Prepared by: H. Masuhara	
From: Solution Support Sec., Solution Support Dept.			
Classification:	<input type="checkbox"/> Troubleshooting	<input type="checkbox"/> Part information	<input type="checkbox"/> Action required
	<input type="checkbox"/> Mechanical	<input type="checkbox"/> Electrical	<input type="checkbox"/> Service manual revision
	<input type="checkbox"/> Paper path	<input type="checkbox"/> Transmit/receive	<input type="checkbox"/> Retrofit information
	<input type="checkbox"/> Product Safety	<input checked="" type="checkbox"/> Other (Firmware)	<input checked="" type="checkbox"/> Tier 2

This RTB has been issued to announce the firmware release information for the **Endpoint Service Tools**.

Version	Program No.	Effective Date	Availability of RFU
<b><i>1.0.6</i></b>	<b><i>D5691011106</i></b>	<b><i>September 2015 production</i></b>	<b><i>Not available</i></b>
1.0.5	D5691011105	November 2014 production	Not available
1.0.4	D5691011104	September 2013 production	Not available
1.0.1	D5691011101	March 2011 production	Not available
1.0	D5690011	1st Mass production	Not available

**Note: Definition of Availability of RFU via @Remote**

“Available”: The firmware can be updated via RFU or SD card.

“Not available”: The firmware can only be updated via SD card.

Version	Modified Points or Symptom Corrected
<b><i>1.0.6</i></b>	<b><i>1) Device Support Changes</i></b> <b><i>Intelligent Device Manager -MFP Client V1.0.6 now supports the following devices:</i></b> <b><i>Aficio SP C821DN / Aficio SP C831DN / MP 3053SP / MP 3353SP / MP C5503SP/ MP C6502SP / SP 4510SF / SP 4520DN / SP 6430DN / MP 3054SP / MP 4054SP / MP 6054SP</i></b>
1.0.5	1) Device Support Changes Intelligent Device Manager - MFP Client V1.0.5 now supports the following devices (the V1.0.4 limitation has been resolved): Aficio MP C3000 / Aficio MP C4500 / Aficio MP 5500 / Aficio MP 6000 / Aficio MP 7000 / Aficio 3224C / Aficio 3245C / Aficio 3035 / Aficio 3045 2) Specification Changes - Service Tool supports overwrite installations. 3) Fixed: - Installation was failing on some devices.

**Reissued: 14-Sep-15**

Model: Endpoint	Date: 18-Oct-11	No.: RD569002c
Version	Modified Points or Symptom Corrected	
1.0.4	1) Others <ul style="list-style-type: none"><li>- The Intelligent Device Manager-MFP Client V1.0.4 Service Tools can be used for installing the Intelligent Device Manager-MFP Client (V1.0.0-V1.0.4).</li><li>- The Intelligent Device Manager-MFP Client V1.0.4 Service Tools have had a "Flash Memory" selection added as an install destination for 12A and later device models.</li><li>- Service Tools v1.0.4 does NOT support the following devices: Aficio 3224C/Aficio 3245C/Aficio 3035/Aficio 3045/Aficio MP 201SPF</li></ul>	
1.0.1	1) Others <ul style="list-style-type: none"><li>- Service Tools of Intelligent Device Manager-MFP Client v1.0.1 can be used for installing the Intelligent Device Manager -MFP Client (v1.0.0-v1.0.2) to the following devices: Aficio MP C2500/Pro C900S/Aficio MP 4001/Aficio MP 2851/Aficio MP 3351/Aficio MP C6501/Aficio MP C3001/Aficio MP C3501/Aficio MP C4501/Aficio MP C5501/Aficio SP 6330N/Aficio SP 4310N/Aficio SP 5200DN/Aficio SP 5210DN/Aficio SP 5210SR/Aficio SP C320DN</li><li>- Service Tools v1.0.1 does NOT support the following devices: Aficio 3224C/Aficio 3245C/Aficio 3035/Aficio 3045/Aficio MP 201SPF</li></ul>	
1.0	1st Mass production	