

MODIFICATION BULLETIN NO. K50-221

ISSUED ON Jan. 15, 1995

Model		K50 220V Version					Date of Modification	
Modified Article		PSU Engine Pack					Execution Date	
Reason for Modification		<div><div><input type="checkbox"/> Parts catalog correction</div><div><input type="checkbox"/> Vender change</div></div> <div><div><input type="checkbox"/> To meet standards ()</div><div><input type="checkbox"/> Part standardization</div></div> <div><div><input type="checkbox"/> To facilitate assembly</div><div><input type="checkbox"/> To improve reliability</div><div><input checked="" type="checkbox"/> Other</div></div> <div>Ricoh has decided not to supply the Engine Pack because incorrect installation of the Engine Pack in the field has been the cause of serious problems with the PSU. If the Engine Pack is defective, please replace the PSU but do not replace the Engine Pack of the PSU.</div>						
Old Part No.	New Part No.	Description	Q'ty Used Old ↔ New	Interchange-ability	Remarks	Parts Catalog		
						Index No.	Page	
N6016595	—	Engine Pack			Not available as a spare part			
<div>S.Hamano Assistant General Manager 2nd T.S.Sec. Int'l Marketing Group</div>								