

MODIFICATION BULLETIN NO. BD-001

ISSUED ON June 14th, 1994

Model	Barbara Dash (for Ricoh Version)	Date of Modification
Modified Article		Execution Date
Reason for Modification	<input checked="" type="checkbox"/> Parts catalog correction <input type="checkbox"/> Vender change <input type="checkbox"/> To meet standards () <input type="checkbox"/> Part standardization <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability <input type="checkbox"/> Other	

Old Part No.	New Part No.	Description	Q'ty Used Old → New	Interchange- ability	Remarks	Parts Catalog	
						Index No.	Page
H0937711		Washer - Thermal Head	1 → 0			*	7-3
H0937702		Screw - M3 x 5	1 → 0			*	7-3
H0938506	H0938512	PCB - SBU	1 → 1			122	7-4
	H0938549	PCB - LIU : Universal	0 → 1			126	7-5
H0535028	H0535023	Monitor Speaker	1 → 1			140	7-5
H0937907	52144221	Rubber Foot	1 → 1			*	7-5
	H0938317	Harness - LIU-FDU	0 → 1			*	7-6

S.Hamano
 Assistant General Manager
 2nd T.S.Sec. Int'l Marketing Group

MODIFICATION BULLETIN NO.BD-002

ISSUED ON June 14th,1994

Model	Barbara Dash (Except Ricoh Version)	Date of Modification
Modified Article		Execution Date
Reason for Modification	<input checked="" type="checkbox"/> Parts catalog correction <input type="checkbox"/> Vender change <input type="checkbox"/> To meet standards () <input type="checkbox"/> Part standardization <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability <input type="checkbox"/> Other	

Old Part No.	New Part No.	Description	Q'ty Used Old → New	Interchange- ability	Remarks	Parts Catalog	
						Index No.	Page
H0938506	H0938512	PCB - SBU	1 → 1			122	7-4
H0938402		Power Cord - BF type	1 → 0			138	7-4
H0938403		Power Cord - CH type	1 → 0			138	7-4
H0535028	H0535023	Monitor Speaker	1 → 1			140	7-4
H0937907	52144221	Rubber Foot	1 → 1			*	7-4
	H0938317	Harness - LIU : Universal	0 → 1			*	7-5

S.Hamano
 Assistant General Manager
 2nd T.S.Sec. Int'l Marketing Group

MODIFICATION BULLETIN NO. BD-003ISSUED ON June 14th, 1994

Model		Date of Modification
Modified Article		Execution Date
Reason for Modification	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> Vender change <input type="checkbox"/> To meet standards () <input type="checkbox"/> Part standardization <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability <input checked="" type="checkbox"/> Other <p>The software has been changed to introduce the Austrian PTT requirements and to include Czech, Polish, Turkish, and Slovenian instead of Dutch, Swedish, Portuguese, and Norwegian.</p>	From 1st production of May,1994.

Old Part No.	New Part No.	Description	Q'ty Used Old → New	Interchange- ability	Remarks	Parts Catalog	
						Index No.	Page
H0967106	H0967107	IC - Programmed ROM : BD : A, Univ.	1 → 1	X / O	Only for Austrian and Universal versions	*	7-5

S.Hamano
Assistant General Manager
2nd T.S.Sec. Int'l Marketing Group

MODIFICATION BULLETIN NO. BD-004ISSUED ON June 30, 1994

Model	Barbara Dash	Date of Modification
Modified Article	Software	Execution Date
Reason for Modification	<input type="checkbox"/> Parts catalog correction <input checked="" type="checkbox"/> To meet standards () <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Vender change <input type="checkbox"/> Part standardization <input type="checkbox"/> To improve reliability <input type="checkbox"/> Other <p>To introduce the Dutch and Swiss PTT requirements, the software has been changed.</p>	From 1st production of the Dutch version

Old Part No.	New Part No.	Description	Q'ty Used Old → New	Interchange- ability	Remarks	Parts Catalog	
						Index No.	Page
H0967106B	H0967106C	IC - Programmed ROM: BD	1 → 1	X / O		*	*

S. Hamano
Assistant General Manager
2nd T.S.Sec. Int'l Marketing Group

MODIFICATION BULLETIN NO. BD-005

ISSUED ON Sep. 14, 1994

Model	Barbara Dash (PF03, FAX250)	Date of Modification
Modified Article	Software	Execution Date
Reason for Modification	<div> <input type="checkbox"/> Parts catalog correction <input type="checkbox"/> Vender change <input checked="" type="checkbox"/> To meet standards (Italy) <input type="checkbox"/> Part standardization <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability <input type="checkbox"/> Other </div>	From June production in 1994.

[illegible]

S.Hamano
Assistant General Manager
2nd T.S.Sec. Int'l Marketing Group

MODIFICATION BULLETIN NO. BD-006ISSUED ON Jul. 13, 1995

Model	Barbara Dash						Date of Modification	
Modified Article	FCE						Execution Date	
Reason for Modification	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To meet standards () <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Vender change <input checked="" type="checkbox"/> Part standardization <input type="checkbox"/> To improve reliability (for spare part control) <input type="checkbox"/> Other						The new part numbers are registered in July 1995.	
Note: ROM A = H0967106 ROM B = H0967107								
Old Part No.	New Part No.	Description	Q'ty Used Old → New	Interchange- ability	Remarks	Parts Catalog		
						Index No.	Page	
H095 8509		(510350942171) PCB-FCE-RF03 w/o ROM	1 → 0					
	H095 9550	(510350942183) PCB-FCE-RF03- with ROM A	0 → 1					
	H095 9551	(510350942171) PCB-FCE-RF03- with ROM B	0 → 1					
H096 8509		(510350942621) PCB-FCE-RF03 w/o ROM	1 → 0					
	H096 9550	(510350942293) PCB-FCE-FAX250 with ROM A	0 → 1					
	H096 9551	(510350942621) PCB-FCE-FAX250 with ROM B	0 → 1					
M. Iwasa Manager 2nd T.S.Sec. Int'l Marketing Group								