

Model: Model K3		Date: 23-Jan-03	No.: MH310004
Modified Article: Parts Catalog Corrections		Prepared by: M. Mano	
From: Technical Services Sec. Service Planning Dept.			
Reason for Modification:	<input checked="" type="checkbox"/> Parts catalog correction <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Part standardization	<input type="checkbox"/> Vendor change <input type="checkbox"/> To improve reliability <input type="checkbox"/> Other	<input type="checkbox"/> To meet standards ()

The following parts have been modified to ensure the harness is not pinched when the PFU is installed.

Optional PFU (H206)

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
H3103538	H3103539	Connector Bracket	1	X/O	9	5	
H3105289	H3105270	Upper Relay Harness	1	X/O	9	13	
11050199	11050487	Harness Clamp	1	X/O	9	101	



Part Change Information List

Date: December 29, 2009

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
PFU Type510 for Kaiser 3	H206	200912		H3105042	H2065042	Magnetic Clutch: Paper Feed: H310	1	1	O/O		7	9						