#### RICOH

# Modification Bulletin

Model: AD330	Date: 28-F	eb-97	No: 001	1/1				
Modified Article: D	Ouplex Unit Board	Prepared by: K. Ugaeri						
From: QAC 2nd Field Information Dept.				Checked by: S. Fujii				
Reason for Modification:		☐ Vendor ch ☐ To improve	Ū	☐ To meet standards (  )				

To standardize the parts, the duplex unit board has been changed.

Old part	New part	Description	Qty	Int	Page	Index	Note
number	number						
G6945340	G6945350	Duplex Unit Board	1 - 1	x/o	2	5	

RICOH

### Modification Bulletin

**PAGE: 1/1** 

Model: AD330 Date				e: 31-Aug-97	No: 2
Modified Article: Parts catalog correction			Prepared by: M.Horiike		
From: QAC 2nd Field Information Dept.					
Reason for	□ Parts catalog correction	☐ Vend	lor ch	ange 🔲 To n	neet standards
Modification:	$\square$ To facilitate assembly	$\square$ To improve reliability $\qquad (\qquad )$			)
	☐ Part standardization	Othe	r		

The following unit number for the Inverter Unit has been newly set up.

Old part number	New part number	Description	Qty	Int	Page	Index	Note
-	G6944501	Inverter Unit	1	-	7	*	-

Please add this part number before Index No.1 on page 7 of your part s catalog.

This unit number includes all parts on page 7.

# RIGOH

Model: AD330

Reason for

Modification:

Modified Article: Mylar-Inverter Guide Plate

From: QAC Field Information Dept.

## Modification Bulletin

☐ Other

Date: 15-Apr-9			8	No: 3	
		Prepared	l by: κ.ι	Jgaeri	
	-				
☐ Vendor change			☐ To n	neet standards	,
☐ To improve reliability			(	)	

**PAGE: 1/1** 

The following should be corrected. Please correct your part catalog.

□ Parts catalog correction

☐ To facilitate assembly

Part standardization

The mylar is included in the inverter guide plate (G6944725, index no. 22, page 5).

