

Model: Russian-C Duplex Unit (AD360)		Date: 11-Jan-08	No.: MA896001
Modified Article: Exchange Pawl		Prepared by: S. Tomoe	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	<input type="checkbox"/> Parts catalog correction <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> Part standardization	<input type="checkbox"/> Vendor change <input type="checkbox"/> To improve reliability <input checked="" type="checkbox"/> Other	<input type="checkbox"/> To meet standards ()

Change: The materials for these parts were changed to more environmentally-friendly types.

Reason: This is part of Ricoh's ongoing application of in-house environmental standards.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
A8964651	A8964656	Exchange Pawl	1-1	O/O	3	14	



Part Change Information List

Date: February 28, 2013

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
R-C1 Duplex Unit (AD360)	A896	201302		A8964717	A8964718	LINK DC SOLENOID ASS'Y	1	1	O/O		5	17					V0801113	