

|  |  |                       |               |
|--|--|-----------------------|---------------|
| Model: K-P1 Duplex Unit (G552)                     |  | Date: 22-Jun-09       | No.: RG552001 |
| Subject: PCB/Harness                               |  | Prepared by: Y.Murata |               |
| From: 1st Tech. Support Sec. Service Support Dept. |  |                       |               |
| Classification:                                    | <input type="checkbox"/> Troubleshooting <input checked="" type="checkbox"/> Part information <input type="checkbox"/> Action required<br><input type="checkbox"/> Mechanical <input type="checkbox"/> Electrical <input type="checkbox"/> Service manual revision<br><input type="checkbox"/> Paper path <input type="checkbox"/> Transmit/receive <input type="checkbox"/> Retrofit information<br><input type="checkbox"/> Other (      ) |                       |               |

| Old P/N  | New P/N         | Description           | Q'ty | Int | Page | Index | Note |
|----------|-----------------|-----------------------|------|-----|------|-------|------|
| G8065100 | <b>G8065111</b> | PCB:KIR-P4:DCB2       | 1    | X/X | 3    | 10    |      |
| G8067914 | <b>G8067925</b> | HARNESS:SAFETY SWITCH | 1    | X/X | 7    | 15    |      |
| -        | <b>G8067965</b> | PCB:HARNESS:ASS'Y     | 1    | -   | 3    | 31    |      |

## Change:

- 1) The shapes of the harness connector (PCB side, circled in red below) and the PCB connector were changed.
- 2) The PCB/harness assembly was added.

**Reason:** Harness vendor change.

p.6

