

Reissued:10-Sep-09

Model: K-P4 Duplex Unit AD Type 610 (G806)	Date: 22-Jun-09	No.: RG806001a
--	-----------------	----------------

## RTB Reissue

The items in ***bold italics*** were corrected or added.

Subject: PCB/Harness		Prepared by: Y.Murata	
From: 1st Tech. Support Sec. Service Support Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Other (      )	<input checked="" type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information



Old P/N	New P/N	Description	Q'ty	Int	Page	Index	Note
G8065100	<b>G8065111</b>	PCB:KIR-P4:DCB2	1	X/X	3	10	
G8067914	<b>G8067925</b>	HARNESS:SAFETY SWITCH	1	X/X	7	15	
-	<b>G8067965</b>	PCB:HARNESS:ASS'Y	1	-	3	31	

## Change:

- 1) The shapes of the harness connector (PCB side, circled in red below) and the PCB connector were changed.
- 2) The PCB/harness assembly was added.

**Reason:** Harness vendor change.

p.6



**Cut-in Serial number:**  
**Q3696700001**