RIGOH

Reason for

Modification:

Model: Bellini Printer Controller Type A

From: Technical Services Dept., GTS Division

Modified Article: ROM DIMM

Modification Bulletin

Date: 27-Dec-00			No.: MB336001			
Р	Prepared by: A. Sasaki					
☐ Vendor change ☐ To improve reliability		To meet	standards			

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
	B338 5700	ROM DIMM (Tool)	1		3	21	*1

☐ Other

*1: New index

PAGE: 1/1

Please add the above part to the parts catalog.

This is a service tool to be used when the printer controller firmware cannot be downloaded from a flash memory card.

Please refer to the service manual for the downloading procedure.

□ Parts catalog correction

☐ To facilitate assembly

☐ Part standardization