
Modification Bulletin

Model: Adonis-C2 B	Bridge Unit	e: 22-Apr-02	2	No.: MB397001		
Modified Article: P	arts Catalog Correction	Prepared	Jrushihara			
From: Technical Ser	vices sec. Service Planning D					
Reason for	Parts catalog correction	U Venc	lor ch	ange	🗌 To m	neet standards
Modification:	To facilitate assembly	To improve reliability			()
	Part standardization	Othe	r			

Please add the following description to your parts catalogues.

RIGOH

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
	A6884466	Rear Side Plate	1		3	29	



RICOH	Part Change In	formation List					Dat	e: Fe	bruary 2	29, 2012	2			
Model	Code PCII Nr PCIL Old part New part	Description	Old O'ty New O'ty	Int	3DPC	Page	Index	Set	Set Int	BTB	Note	Ref Nr	ECN Nr	

Model	Code	PCIL Nr.	FUIL	Old part	New part	Description	Old O'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
Model	Code	FOIL NI.	Correction	number	number	Description	Old Q ly	New Q ty		3010	rage	macx	Jei	Set IIIt	nib	Note	FIGH NI.	LONINI
											3	3						
A-C2 Bridge Unit	B397	201202		AW020098	AW020179	PAPER FEED SENSOR	2	2	X/O		5	20					V1200119	