

Model: Model AT-C1 Bridge Unit (BU3000)		Date: 28-Jan-09	No.: MB227001
Modified Article: Discharge brush on BU3000		Prepared by: M.Kumagai	
From: 2nd Tech. Support Sec. Service Support Dept.			
Reason for Modification:	☒ Parts catalog correction ☒ Vendor change ☐ Other ☐ To facilitate assembly ☐ To improve reliability ☐ To meet standards ☐ Part standardization ☐ Product Safety ()		

Change: The following part number was changed.

Reason: Vender change

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B2274667	AA120138	DISCHARGE BRUSH:EXIT	1	O/O	5	26	



Part Change Information List

Date: May 30, 2009

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number
AT-C1 Bridge Unit (BU3000)	B227	200905		AA120129	AA120137	DISCHARGE BRUSH:JOINT UNIT:FIN	1	1	O/O		3	16					V0803726
AT-C1 Bridge Unit (BU3000)	B227	200905			M3214743	COVER:FRAME	0	1	X/O		4	39			Y		V0804519



Part Change Information List

Date: December 29, 2009

Model	Code	PCIL Nr.	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref. Nr.	ECN Nr.
AT-C1 Bridge Unit (BU3000)	B227	200912		AB030788	AB030827	PULLEY:MECHANICAL ROLLER CLUTCH:JOINT UNIT	1	1	O/O		3	12					V0803093	8071496