1നന	ПП
[(片(D)	۱ñ۱

Technical Bulletin


Model: AT-C1c/d Da				e: 22-Jul-()9	No.: RB227001			
Subject: Cover Frame for BU3000					Prepared by: M. Kumagai				
From: 2nd Tech Support Sec. Service Support Dept.									
Classification:	ation: Troubleshooting 🖂 Part inform		ormat	tion	required				
		☐ Electrical		☐ Servi		ice manual revision			
	☐ Paper path	☐ Transmit/rece		eive	☐ Retrof	fit information			
	☐ Product Safety	Other ()					

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
-	M3214743	Cover Frame	1		3	32	*

Change/Reason: An additional cover for the frame was added.

*New index number

.BRIDGE UNIT 1 (B227)



RICOH

Technical Bulletin

PAGE: 1/1

Model: AT-C1 Bridge Unit (BU3000) Date			e: 21-Dec	-09	No.: RB227002				
Subject: Parts information					Prepared by: M. Kumagai				
From: 1st Overseas Tech Support Sec., 1st PQM Dept.									
Classification:	☐ Troubleshooting ☐ Part inform			tion	☐ Action	required			
	☐ Mechanical	☐ Electrical		☐ Servi		ice manual revision			
	☐ Paper path	☐ Transmit/rece		ceive Retr		fit information			
	☐ Product Safety	\square Other ()	☐ Tier 2				

Change / **Reason:** The following part number was corrected.

Incorrect part	Correct part	Description		Q'ty	Int	Page	Index	Note
number	number							
AB030789	AB030788	PULLEY:MECHANICAL CLUTCH:JOINT UNIT	ROLLER	1		3	12	

1.BRIDGE UNIT 1 (B227)

