

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Anatolia	D778	201501			D7783724	HEAT SINK:JOINT UNIT:SPACER:LONG	0	2		Y							V1403948	14120682
Anatolia	D778	201501			D7783725	HEAT SINK:JOINT UNIT:SPACER:SHORT	0	2		Y							V1403948	14120682
Anatolia	D778	201501		04543006N	03603006N	SCREW - M3X6	8	8	O/O	Y							V1500107	14120907
Anatolia	D778	201501		04543006N		TAPPING SCREW:ROUND POINT:3X6	1	10		Y							V1403948	14120682



Part Change Information List

Date: February 27, 2015

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Bridge Unit BU5010	D778	201502			16072247	FERRITE CORE:K3 NF-55(N)BK0	0	2		Y							V1500417	14121162
Bridge Unit BU5010	D778	201502		04544008N		TAPPING SCREW:ROUND POINT:4X8	124	122		Y							V1500421	15010997
Bridge Unit BU5010	D778	201502			54082035	STEPPED SCREW - M4	0	1		Y							V1500421	15010997



Part Change Information List

Date: June 4, 2015

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Bridge Unit BU5010	D778	201504		D7785321	D7785324	HARNESS:CONNECTING:SENSOR:JOINT UNIT:ASS'Y	1	1	X/O	Y							V1500417	14121162
Bridge Unit BU5010	D778	201504		D7783723	D7783726	HEAT SINK:JOINT UNIT	1	1	X/O	Y			A				V1500107	14120907
Bridge Unit BU5010	D778	201504		D7783724	D7783727	HEAT SINK:JOINT UNIT:SPACER:LONG	2	2	O/X	Y			A				V1500107	14120907
Bridge Unit BU5010	D778	201504		D7783725	D7783728	HEAT SINK:JOINT UNIT:SPACER:SHORT	2	2	X/O	Y			A				V1500107	14120907



Part Change Information List

Date: July 2, 2015

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q' ty	New Q' ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Bridge Unit BU5010	D778	201506		D7773126	D5171198	TIMING PULLEY:DRIVE:T25S2M	1	1	O/O	Y							V1501539	15040775
Bridge Unit BU5010	D778	201506			16072247	FERRITE CORE:K3 NF-55(N)BK0	0	2		Y							V1500417	14121162



Part Change Information List

Date: August 3, 2015

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Bridge Unit BU5010	D778	201507			04543008N	TAPPING SCREW:ROUND POINT:3X8	---	1		Y							V1501862	15041418



Part Change Information List

Date: December 2, 2015

[illegible]



Part Change Information List

Date: January 5, 2015

[illegible]



Part Change Information List

Date: July 1, 2016

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Bridge Unit BU5010	D778	201607			11029429	CONNECTOR:1-1612257-2		1		Y								



Part Change Information List

Date: November 2, 2016

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Bridge Unit BU5010	D778	201610		D3551195	D7781196	TORSION SPRING:DETENT:8N	2	2	O/O	Y				0			V1602828	16080406



Part Change Information List

Date: May 12, 2017

[illegible]



Part Change Information List

Date: February 1, 2018

[illegible]

Model	Code	PCIL Number	PCIL Correction	Old part number	New part number	Description	Old Q'ty	New Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
Bridge Unit BU5010	D778	201901			D7781302	DECAL:MISFEED REMOVAL:ANATOLIA-B	0	1		Y							V1802511	17060977

