RICOH

Modification Bulletin

PAGE: 1/1

Model: Be-C1: Bridge Unit BU6500			Da	Date: 13-Feb-09		No.: MD407001	
Modified Article: Cover: Interface			Prepared by: F.Noguchi				
From: 2nd Tech. Support Sec. Service Support Dept.							
Reason for	Parts catalog correction	U Vendor	cha	ange	Other		
Modification:	To facilitate assembly	To improve relia		e reliability	🗌 To mee	et standards	
	Part standardization	Product Safety		afety	()	

Old part	Description	Q'ty	Page	Index	Note
number					
D4361244	COVER:INTERFACE: KEY CARD	1 - 0	3	1	
B8891694	COVER:INTERFACE: SCANNER:DIVISION	1 - 0	3	2	

Change: The parts in the table were deleted as service parts. **Reason:** These parts are now included in the Be-C1 accessories.

MODEL NAME	V/Hz	DESTINATION	CODE	SERIAL NO.
Bridge Unit BU6500	120/60	USA, Canada, S. America Europe, Asia, Oceania, etc	D407-17	V06902XXXXX