

=====  
\*\*\* Basic Information \*\*\*  
=====

[Create date] 2018/11/19

-----  
[Program Name] BufferPassUnit

-----  
[Version] 02.020:10

-----  
[PCB No.]

-----  
[Interchangeability] X / O

-----  
[Other Firmware Requirements] None

-----  
[PCB Requirements] None

-----  
[Software category] Normal Release

-----  
[Release category] Normal Release

-----  
[Program category] Firmware

-----  
Exported to(language) GEN(all)

[Firmware No.] D5481702C

[File Information]

File Name        D5481702C.fwu

File Type        Module for Service

Size             0.25 MB ( 262848 byte )

[File Information]

File Name        D5481702C.rfu

File Type        Module for Remote Upgrade

Size             0.26 MB ( 270592 byte )

[Availability of RFU] No

-----  
[Production reflection] 2013/03  
-----

=====  
\*\*\* Note \*\*\*  
=====

[Note]  
  
-----

=====  
\*\*\* Important Notes \*\*\*  
=====

[Important Notes]  
  
-----

=====  
\*\*\* Modification History \*\*\*  
=====

=====  
[Modifications made:]

Rank C

Buffer Pass Unit for Pro C51xx series:

- First release

Buffer Pass Unit for Pro C651/751 series:

- Changes made to Buffer Pass Unit Type 5020 (D751) were also  
applied to Buffer Pass Unit Type 5010 (D548) for standardization.

-----  
[Modification history]

-----  
Version 02.010:09

Symptom Corrected:

Jams when feeding paper longer than 614mm.

-----  
Version 02.000:09

1st Mass production