RIGOH

Modification Bulletin

PAGE: 1	1/1
---------	-----

Model: Model-J CF			Date: 26-May-03		3	No.: MG570001
Modified Article: DIMM			Prepared by: Hideki Taguchi			
From: 1st Tech. Support Sec. Service Support Dept.						
Reason for	☐ Parts catalog correction	☐ Vendor chang		ange	☐ To n	neet standards
Modification: ☐ To facilitate assembly ☐ To improv		nprove	e reliability	()	
	☐ Part standardization	☐ Othe	r			

The contents of the System firmware DIMM have been changed. See RTB #RG570002 for the v1.07 firmware history.

Major changes made:

• The meter click counter specification has been changed so that copies made in SP mode are not counted up.

Note: Be sure to use v1.07 with engine main firmware v1.15e or later, as SC999 will occur with older engine main versions.

• Fixed centering problem when printing onto 12" x 18" paper.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G5705335	G5706687	DIMM 1 - System	1 – 1	X/X	11	6	

Trou (Supuri) I Toudot				
Model	V/Hz	Destination	Code	Serial Number
Copier Feature Expander Type 3800C	120V, 60Hz	USA, Canada	G570-17	P6720400001
Copier Feature Expander Type 3800C	220 - 240V, 50/60Hz	Europe, etc.	G570-26	4H20320001
Copier Feature Expander Type 3800C	220 - 240V, 50/60Hz	Europe, etc.	G570-27	P6720300001
Copier Feature Expander Type 3800C	220 - 240V, 50/60Hz	Asia	G570-29	P6720300328

\mathbb{Q}	ጠ	叮
(K)		ᄖ

PA	G	F٠	1	11
$\Gamma \wedge$	J	L .		•

Model: Model-J CF Da			Date	e: 29-May-0	3	No.: MG570002
Modified Article: DIMM			Prepared by: H.Taguchi			
From: 1st Tech. Support Sec. Service Support Dept.						
Reason for	☐ Parts catalog correction	☐ Vendor char		ange	☐ To n	neet standards
Modification:	☐ To facilitate assembly			e reliability	()
	☐ Part standardization	☐ Othe	r			

The Euro currency symbol has been added to 112 fonts in the following DIMM.

Related bulletins: #Rgene011, #RG570003f (Printer v1.11).

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G5706687	G5706691	DIMM 1 - System	1 – 1	X/O	11	6	

110= (00.000) 1 1 0 0.000				
Model	V/Hz	Destination	Code	Serial Number
Copier Feature Expander Type 3800C	120V, 60Hz	USA, Canada	G570-17	P6721000387
Copier Feature Expander Type 3800C	220 - 240V, 50/60Hz	Europe, etc.	G570-26	4H21020026
Copier Feature Expander Type 3800C	220 - 240V, 50/60Hz	Europe, etc.	G570-27	P6721001020
Copier Feature Expander Type 3800C	220 - 240V, 50/60Hz	Asia	G570-29	P6721001394

\mathbb{C}	ПП
(K(0)	問

PAGE:	1/1

Model: Model-J CF			Date	te: 29-May-03		No.: MG570003
Modified Article: Sensor Stopper			Prepared	by: н.1	Гaguchi	
From: 1st Tech. Support Sec. Service Support Dept.						
Reason for	☐ Parts catalog correction	☐ Vend	lor ch	ange	☐ To n	neet standards
Modification:	☐ To facilitate assembly			e reliability	()
	☐ Part standardization	☐ Othe	r			

The shape of the following has been changed to ensure it does not interfere with the Rear Scanner Cover. The part name was also changed.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
A1931793		Scanner Home Sensor Stopper	1 – 1	X/O	7	23	
	G5701225	Shielding Plate					

Model	V/Hz	Destination	Code	Serial Number
Copier Feature Expander Type 3800C	120V, 60Hz	USA, Canada	G570-17	P6720500051
Copier Feature Expander Type 3800C	220 - 240V, 50/60Hz	Europe, etc.	G570-26	4H20620001
Copier Feature Expander Type 3800C	220 - 240V, 50/60Hz	Europe, etc.	G570-27	P6720500445
Copier Feature Expander Type 3800C	220 - 240V, 50/60Hz	Asia	G570-29	P6720500670

വത്യ	ПП
1G0	lñl

ec-03	No.: MG570004	

PAGE: 1/1

Model: Model-J CF Date			e: 25-Dec-03		No.: MG570004		
Modified Article: Lens Block					Prepared by: H.Taguchi		
From: 1st Tech. Support Sec. Service Support Dept.							
Reason for	leason for Parts catalog correction Vendor ch		lor ch	ange	☐ To n	neet standards	
Modification: ☐ To facilitate assembly ☐ To improve		To improve reliability (()		
	☐ Part standardization	Othe	r				

The adhesive and adhesive method for the lens holder assembly components (CCD control board) has been improved to provide greater adhesive integrity against heat and operational stress, which can sometimes cause SC142.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G5702921—		Lens Block	1 - 1	X/O	7	5	
	→ G5702930	Lens:Holder:Ass'y					

102 (04)								
Model	V/Hz	Destination	Code	Serial Number				
Copier Feature Expander Type 3800C	120V, 60Hz	USA, Canada	G570-17	P67311xxxxx				
Copier Feature Expander Type 3800C	220 - 240V, 50/60Hz	Europe, etc.	G570-26	4H2113xxxxx				
Copier Feature Expander Type 3800C	220 - 240V, 50/60Hz	Europe, etc.	G570-27	P67311xxxxx				
Copier Feature Expander Type 3800C	220 - 240V, 50/60Hz	Asia	G570-29	P67311xxxxx				

വത്യ	ПП
1G0	lñl

PAGE:	1/1
-------	-----

Model: Model-J CF Date			e: 16-Feb-04		No.: MG570005	
Modified Article: Xenon Lamp					by: H.1	Гаguchi
From: 1st Tech. Support Sec. Service Support Dept.						
Reason for	son for Parts catalog correction Vendor cha		ange	☐ To n	neet standards	
Modification:	☐ To facilitate assembly			☐ To improve reliability)
	☐ Part standardization	☐ Othe	r			

The density of the coating applied to the Xenon lamp electrodes has been increased to further improve the efficiency of lamp warm-up.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number					ļ	
G5702725	B1161800	Xenon Lamp – MM8	1 – 1	X/O	9	8	

HOE (bapan) I roddetion								
Model	V/Hz	Destination	Code	Serial Number				
Copier Feature Expander Type 3800C	120V, 60Hz	USA, Canada	G570-17	P67307xxxxx				
Copier Feature Expander Type 3800C	220 - 240V, 50/60Hz	Europe, etc.	G570-26	4H2073xxxxx				
Copier Feature Expander Type 3800C	220 - 240V, 50/60Hz	Europe, etc.	G570-27	P67307xxxxx				
Copier Feature Expander Type 3800C	220 - 240V, 50/60Hz	Asia	G570-29	P67307xxxxx				

 0	
(GO	ш
1111211111	151
1001001	ш

Reason for

Modification:

Model: Model-J CF

Modified Article: ADF Exposure Glass

From: 1st Tech. Support Sec. Service Support Dept.

☐ Parts catalog correction

☐ To facilitate assembly

☐ Part standardization

Modification Bulletin

Dat	e: 11-May-0)4	No.: MG570006
	Prepared	by: H.7	raguchi
ot.			
☐ Vendor ch	ange	☐ To n	neet standards
☑ To improv	e reliability	()

PAGE: 1/1

The following was changed, because a coat was added to the exposure glass surface to prevent contamination.

☐ Other

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B3516522		ADF Exposure Glass	1-1	X/O	3	8	
	→ BC012002	Exposure Glass:Sheet Through:344X20					



Part Change Information List

Date: January 31, 2011

Model	Code PCIL Nr. PCIL	Old part New part	Description	Old Q'tv New Q'tv In:	3DPC Page	Index Set Set Int	RTR	Note Ref. Nr.	ECN Nr
	Correction				. JDI O Tage	maex Set Set Int	IIID		ECIN INI.
J CF	G570 201101	A1931767 M0261815 CLAMP:	MIRROR:NO.1	2 2 0/0	9	9 22		V1001619	10070454



Part Change Information List

Date: June 29, 2018

				PCIL	Old part	New part													
	Model	Code	PCIL Number	Correction	number	number	Description	Old Q'ty Nev	/ Q'ty	Int	3DPC	Page	Index	Set	Set Int	RTB	Note	Ref Number	ECN Number
J CF	-	G570	201806		B1801709	B2381814	PULLEY:DRIVE WERE:REAR:SUB-ASS'Y	1	1	X/0	N	9	18			Υ		V1800574	