

Model: Cattleya Interface Kit		Date: 15-Nov-99	No.: MA839001
Modified Article: BUSSW Board		Prepared by: T. Itoh	
From: Technical Services Dept., GTS Division			
Reason for Modification:	☐ Parts catalog correction ☐ To facilitate assembly ☐ Part standardization	☐ Vendor change ☐ To improve reliability ☒ Other	☐ To meet standards ()

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
A8485111	A8485112	BUSSW Board	1	X/O	3	9	

Some unnecessary component parts of this PCB, which were necessary only for the Japanese version, have been removed from the overseas versions. The part number has been changed for administration purposes.

NOTE: Refer to RTB #016 for the problem found on the BUSSW Board (#A8485111).

MODEL NAME	V/ Hz	DESTINATION	CODE	SERIAL NUMBER
Controller Interface Type F	120V/ 60Hz	USA, CANADA, TAIWAN	A839-17	H1390800151
Controller Interface Type F	220- 240V 50/60Hz	EUROPE, Asia, Middle East, etc.	A839-27	H1390700144
Controller Interface Type F	120V/ 60Hz	USA	A839-55	From first mass production