

| | | |
|--------------------------------------|----------------|---------------|
| Model: V-C1 Copy Connector type 3260 | Date:19-Jun-09 | No.: RB328001 |
|--------------------------------------|----------------|---------------|

| | | | |
|--|---|--|---|
| Subject: PCB:SDRAM-DIMM:64MB:PBF:ASS'Y | | Prepared by: T.Toriumi | |
| From: 2nd Tech. Support Sec. Service Support Dept. | | | |
| Classification: | <input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Other () | <input checked="" type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive | <input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information |

53. DRIVE SECTION 1 (A292/A293/B098)

| Old part number | New part number | Description | Q'ty | Int | Page | Index | Note |
|-----------------|-----------------|-------------------------------|------|-----|------|-------|------|
| G3305700 | G3305720 | PCB:SDRAM-DIMM:64MB:PBF:ASS'Y | 1-1 | O/O | 3 | 10 | |
| G3305720 | - | PCB:SDRAM-DIMM:64MB:PBF:ASS'Y | 1-0 | - | 3 | 10 | |

Change/Reason: The two parts modifications in the table were mistakenly included in the PCILs listed below. Please ignore this mistaken information, as these parts are **not** used in the Model V-C1 Copy Connector type 3260.

G3305700 → G3305720 PCIL#200903.

G3305720 → (deleted) PCIL#200906