П	വ	M	ПП
	ارتا	(0)	빖

Modification Bulletin

PAGE: 1/1

Model: Mail Box for NAD 30S/30/40 Date			e: 28-Feb-99		No.: 1	
Modified Article: Mail Box 3			Prepared by: S. Tomoe			
From: GTSS Field I	nformation Dept					
Reason for	□ Parts catalog correction □ Vendor ch		or cha	ange	☐ To n	neet standards
Modification:	☐ To facilitate assembly	☐ To imp	orove	e reliability	()
1	☐ Part standardization	☐ Other				

The following should be corrected. Please correct your parts catalog.

Part	Description	Qty	Int	Page	Old	New	Note
number					Index	Index	
G9090340	Spacer	10		7	40	41	
G9090341	Bracket Tension	2		7	41	40	

	儿儿
เเษเบ)[[]

Modification Bulletin

PAGE: 1/1

Model: NAD 30S/30/40 Mail Box Date			∋: 31-May-9	9	No.: MG909002		
Modified Article: Microswitch			Prepared by: S. Tomoe				
From: Technical Se	rvice Dept., GTS Division						
Reason for	□ Parts catalog correction	☐ Vend	lor ch	ange	☐ To n	neet standards	
Modification:	tion: ☐ To facilitate assembly ☐ To impro		prove	e reliability	()	
	☐ Part standardization	☐ Othe	r				

The following should be corrected. Please correct your parts catalog.

Old part	New part	Description	Q'ty	Int	Page	Index	Note
number	number						
G9090428	G9090726	Microswitch	1-1		9	28	
					15	26	

ിഥി	ПП
[(比(0)	۱ñ۱

Modification Bulletin

PAGE: 1/1

Model: NAD 30S/30/40 Mail Box Date			e: 07-Mar-0	0	No.: MG909003	
Modified Article: Feeler Sensor			Prepared by: E. Fukuyama			
From: Technical Se	ervices Dept., GTS Division					
Reason for	□ Parts catalog correction	☐ Vendo	r cha	ange	☐ To m	neet standards
Modification:	ication:		e reliability	()	
	☐ Part standardization	☐ Other				

The following part number should be corrected. Please correct your parts catalog.

Old part number	New part number	Description	Q'ty	Page	Index
G9090235	G9090523	Feeler Sensor	1	9	29