ገጦጠ	ΙПЛ
](G(0)	吅

Reason for

Modification:

Modification Schedule:

Model: Model K-P1/P2 4-bin Mailbox (CS380)

From: 1st Technical Support Sec. Service Support Dept.

☐ Parts catalog correction

From October 2002 production

☐ To facilitate assembly

☐ Part standardization

Modified Article: Main Control Board

Modification Bulletin

☐ Other

	Date	e: 3-Jul-03		No.: MG553001
		Prepared	by: A.	Ishiyama
Dept.				
☐ Vendor change			☐ To n	neet standards
☐ To improve reliability		()	
☐ Othe	r			

PAGE: 1/1

An IC on the PCB has been changed to further minimize any effects of static electricity.

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
G5535105A	G5535110	Main Control Board	1→1	X/O	7	10	

ጦጠ	ПП
(G(I)	$\Box\Box$

Modification Bulletin

PAGE: 1/

Model: Model K-P1/P2 4-bin Mailbox (CS380)			ate: 3-Jul-03		No.: MG553002	
Modified Article: Parts Catalog Correction				Prepared	by: A.	Ishiyama
From: 1st Technical Support Sec. Service Support Dept.						
Reason for	□ Parts catalog correction	☐ Vendor change		☐ To n	neet standards	
Modification:	lodification: \square To facilitate assembly \square To improve		e reliability	()	
	☐ Part standardization	☐ Othe	r			

The following have been added to the Parts Catalog for the above option, as they were found to be missing during catalog revisions in preparation for the K-P3 (G091) launch.

Note: The Parts Catalog will be re-released in July 2003 together with the K-P3 Service Manual, containing all recent revisions made.

Incorrect part number	Correct part number	Description	Q'ty	Int	Page	Index	Note
	G5531016	Film: Guide: Auxiliary	0→2		3	20	
	G5531019	Paper Guide Mylar	0→2		3	21	