


Model: Model K-C3 GDI model		Date: 19-Sep-07	No.: MB245020
Modified Article: New part number was added		Prepared by: Y.Yoshida	
From: 1st Tech. Support Sec. Service Support Dept.			
Reason for Modification:	<input checked="" type="checkbox"/> Parts catalog correction <input type="checkbox"/> Vendor change <input type="checkbox"/> Other <input type="checkbox"/> To facilitate assembly <input type="checkbox"/> To improve reliability <input type="checkbox"/> To meet standards <input type="checkbox"/> Part standardization <input type="checkbox"/> Product Safety    (    )		

**Change:** This part was added.

**Reason:** Requests were received from the field.

NEW Part	Description	Q'ty	Int	Page	Index	Note
B8955171	PCB: DONGLE: ASS'Y	0→1	1	3	9	



=====  
\*\*\* Basic Information \*\*\*  
=====

[Create date] 2019/12/20

-----  
[Program Name] GDI without NIC

-----  
[Version] 1.04

-----  
[PCB No.]

-----  
[Interchangeability] X / O

-----  
[Other Firmware Requirements] None

-----  
[PCB Requirements] None

-----  
[Software category] Normal Release

-----  
[Release category] Normal Release

-----  
[Program category] Firmware

-----  
Exported to(language) GEN(all)

[Firmware No.] B8655520C

[File Information]

File Name        B8655520C.zip

File Type        Module for Service

Size             0.94 MB ( 982979 byte )

[Availability of RFU] No

-----  
[Production reflection]

=====  
\*\*\* Note \*\*\*  
=====

[Note]

=====  
\*\*\* Important Notes \*\*\*  
=====

[Important Notes]

=====  
\*\*\* Modification History \*\*\*  
=====

[Modifications made:]

Rank C

Symptom corrected:

- A vulnerability (CVE-2019-14300) to buffer overflows parsing HTTP cookie headers has been fixed.
- A vulnerability (CVE-2019-14305) to buffer overflows in some setting values has been fixed.
- A vulnerability (CVE-2019-14307) to a denial of service attack on setting SMTP values has been fixed.
- A vulnerability (CVE-2019-14308) to a potential buffer overflow sending a crafted LPD packet has been fixed.

-----  
[Modification history]

-----  
Version 1.03

Symptom Corrected:

Printing job speed reduces under the duplex print mode.

-----  
Version 1.02

Supports the K-C3.5L Asia 18 CPM model.

-----  
Version 1.00

1st Mass production