

Model: ADF DF2000		Date: 28-Dec-10	No.: RB813001
Subject: Parts Catalog Correction_Pick up collar and Timing pulley		Prepared by: M.Saiki	
From: 2nd Overseas Tech Support Sec., 2nd PQM Dept.			
Classification:	<input type="checkbox"/> Troubleshooting <input type="checkbox"/> Mechanical <input type="checkbox"/> Paper path <input type="checkbox"/> Product Safety	<input checked="" type="checkbox"/> Part information <input type="checkbox"/> Electrical <input type="checkbox"/> Transmit/receive <input type="checkbox"/> Other ()	<input type="checkbox"/> Action required <input type="checkbox"/> Service manual revision <input type="checkbox"/> Retrofit information <input type="checkbox"/> Tier 2

Old part number	New part number	Description	Q'ty	Int	Page	Index	Note
B3872163	B7892163	PICKUP COLLAR	1- 1	X/X	5	12	#
B3872164	B7892164	TIMING PULLEY – 20Z	1- 1	X/X	5	11	#

X/O as a set

Change: The shapes of the collar and pulley were changed.

Reason: To improve the reliability of the pulley mechanism.

